

ASS. REC. BY:

REF:

CS/CTI 22011805/Dvp³

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: GW 9051P

Policy No. DMCVSNA00125242203

Claims No. SNM22D208490/C02

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBK 4388Z Yr Regn: July 2020

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace Regius c.c. 2754

Colour: 146 770 A/C: Insured / Std / NI / NA

Sp. Reading: silw T/Radio: Insured / Std / NI / NA

Eng/No: 1GD8492066

C/No: GDM 2012009402

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15C

R: -11-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Bridgestone

Front Rear

R/Bal. S mm R/Bal. S mm

L/Bal. S mm L/Bal. S mm

D.O.A. 24/11/2022 D.O.I. 25/11/2022

Survey held at JWG AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Check Taping GW 9051P</u>
<u>22/2/23</u>	<u>Issue of S 4,000 - with 4 days of work (red 23,404.61, 85%)</u>

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) 23/2/23-typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Photos

Others

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Inve (\$)

Report Format: Merimen

Service Charge I.P.P. Fee: LS \$4000

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 9698 8882 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: CHINA TAIPING

Att: Motor Claims Dept

ACCIDENT INVOLVING GW9051P [YOUR INSURED] & GBK4388Z [OUR CLIENT]
ON 25/11/2022.

ESTIMATED REPAIR COSTS FOR GBK4388Z

MODEL : TOYOTA HIACE

<u>QTY</u>	<u>PARTS</u>		<u>AMOUNT</u>
1PC	TAILGATE <i>Denah</i>	1850.00	\$ 2,150.39
1PC	TAILGATE LOGO <i>Hec</i>		\$ 65.29
1PC	TAILGATE REGIUS ACE STICKER <i>Hec</i>	30.00 SH	\$ 159.30
1PC	TAILGATE 1200KG STICKER <i>Hec</i>	20.00 SH	\$ 143.29
1PC	TAILGATE INNER TRIM BOARD <i>HH</i>		\$ 441.92
1PC	TAILGATE INNER BOARD HANDLE <i>HH</i>		\$ 197.00
1PC	TAILGATE CENTER MOULDING <i>HH</i>		\$ 298.00
1PC	TAILGATE WEATHER STRIP <i>Hec</i>	288.20	\$ 395.00
1PC	TAILGATE INNER LOCK <i>HH</i>		\$ 340.00
1PC	TAILGATE STRIKER LOCK <i>HH</i>		\$ 105.00
1PC	TAILGATE WINDSCREEN MOULDING <i>Hec</i>	188.00	\$ 288.21
2PCS	TAILGATE NUMBER PLATE LAMP LH / RH @ \$118.00 EACH <i>HH</i>		\$ 236.00
2PCS	TAILGATE HINGE LH / RH @ \$192.40 EACH <i>HH</i>		\$ 384.80
2PCS	TAILGATE DAMPER LH / RH @ \$498.10 EACH <i>HH</i>		\$ 996.20
2PCS	TAIL LAMP LH / RH @ \$682.39 EACH <i>HH</i>		\$ 1,364.78
2PCS	TAIL LAMP PANEL LH / RH @ \$589.20 EACH <i>HH</i>		\$ 1,178.40
2PCS	TAIL LAMP LOWER GARNISH LH / RH @ \$339.80 EACH <i>HH</i>		\$ 679.60
2PCS	TAIL LAMP LOWER GARNISH BRACKET LH / RH @ \$105.28 EACH <i>HH</i>		\$ 210.56
1PC	REAR BUMPER <i>Denah</i>	599.30	\$ 893.41
1PC	REAR BUMPER CENTER STEP BEAM <i>BT</i>	262.30	\$ 398.00
2PCS	REAR BUMPER SIDE RETAINER LH / RH @ \$58.29 EACH <i>o/s brk</i>		\$ 116.58
1PC	REAR END PANEL INNER <i>Denah</i>	589.30	\$ 1,033.00
1PC	REAR END PANEL OUTER <i>Denah</i>	647.80	\$ 1,082.00
1PC	REAR END PANEL TOP GARNISH <i>HH</i>		\$ 392.81
1PC	REAR SPARE TYRE HOLDER BRACKET <i>HH</i>		\$ 380.00
1PC	REAR SPARE TYRE HOLDER BOLT <i>HH</i>		\$ 60.00
2PCS	REAR FENDER LH / RH @ \$2,769.10 EACH <i>HH</i>		\$ 5,538.20
2PCS	REAR FENDER INNER TRIM LH / RH @ \$891.20 EACH <i>HH</i>		\$ 1,782.40
1PC	REAR EXHAUST PIPE <i>HH</i>		\$ 1,410.00
1PC	REAR EXHAUST MOUNTING <i>HH</i>		\$ 116.00

Handwritten checkmarks and notes on the right side of the table, including '36-20' near the bottom.

1PC	REAR EXHAUST BRACKET HH	\$ 90.00	X
		PARTS SUM: \$ 22,926.14	
		PARTS LESS 25%: \$ 5,731.54	
		PARTS TOTAL: \$ 17,194.61	

4,526.39

3,394.79

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY REAR NUMBER PLATE & GARNISH HH	\$ 100.00	X
*	TO SUPPLY REVERSE CAMERA HH	\$ 600.00	X
*	TO SUPPLY REVERSE SENSOR HF	\$ 300.00	X
*	TO SUPPLY TAILGATE WINDSCREEN SEALANT Huc	\$ 80.00	40/-
*	TO SUPPLY TAILGATE WINDSCREEN DAMPING SEAL H	\$ 30.00	X
*	TO SUPPLY TAILGATE WINDSCREEN INNER SEAL HH	\$ 50.00	X
*	TO SUPPLY TAILGATE CENTER MOULDING CLIPS HH	\$ 50.00	X
*	TO SUPPLY TAILGATE INNER TRIM CLIPS HH	\$ 50.00	X
*	TO SUPPLY TAILGATE TOYOTA STICKER HH	\$ 60.00	X
*	TO SUPPLY TAILGATE HIACE STICKER HH	\$ 60.00	X
*	TO SUPPLY REAR BUMPER CLIPS Huc	\$ 50.00	20/-
*	TO SUPPLY TAIL LAMP CLIPS H	\$ 50.00	X
*	TO SUPPLY TAIL LAMP PANEL SEALANT H	\$ 160.00	X
*	TO SUPPLY REAR END PANEL SEALANT Huc	\$ 150.00	50/-
*	TO SUPPLY TAILGATE 70KM/H STICKER Huc	\$ 50.00	20/-
*	TO SUPPLY REAR FLOOR PANEL TOP BOARD H	\$ 900.00	X
*	TO SUPPLY REAR FLOOR PANEL MATT H	\$ 400.00	X
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 300.00	H
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2,400.00	600/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 2,400.00	600/-
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00	40/-
*	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	\$ 400.00	120/-
*	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	\$ 200.00	60/-
*	TO RNR REAR BUMPER REVERSE SENSOR TO FACILITATE REPAIRS	\$ 120.00	HH
*	TO RNR REVERSE CAMERA TO FACILITATE REPAIRS	\$ 150.00	HH
*	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	\$ 300.00	H
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00	HH
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00	HH

170.00 =

1420.00 =

LABOUR & S/N TOTAL: \$ 10,210.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 27,404.61

4,984.79

4/5 4,000/-

25/11/2022 @ 1600hrs

Not Attached

2 prn

4 dep.

Check part Plus.



LKK Auto



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: