

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011886/DVP3Q2**Date:** 27/02/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00015612200

Claimant Vehicle No : SKQ6690Z **Insured Vehicle No :** GBL6908E

Date of Loss: 24/11/2022 Nature of Claim: TP Claim No: SNM22D208480/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKQ6690Z**

Make & Model: MAZDA 3, 1.5 (A) Engine No: P520233480

Reg. Date: 18/12/2014 (Man. Year: 2014) Chassis No: JM6BM42A8F0149894

Colour: Silver Odometer: 193248 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16

Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,909.52	3,324.16	9,585.36	74.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,600.00	950.00	4,650.00	83.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,509.52	4,274.16	14,235.36	76.91
+ GST 7.00/7.00% (S\$)	1,295.67	299.19	996.48	76.91
Nett Amount (S\$)	19,805.19	4,573.35	15,231.84	76.91

INSPECTION

Date of Assignment: 25/11/2022

Date Inspected: 25/11/2022 Inspected At: JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
AutoPoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Feb 2023)
Parts:	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ6690Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut / Distorted	1,066.00 FL	*1,066.00 FL
2	2		*FRONT BUMPER SIDE RETAINER LH/RH	Serviceable	198.00 FL	*- FL
3	1		*FRONT BUMPER GRILLE	Not Necessary	492.00 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	482.00 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP GARNISH RH	Distorted	298.00 FL	*74.00 FL
6	1		*FRONT BUMPER FOG LAMP GARNISH CHROME RH	Not Necessary	298.00 FL	*- FL
7	1		*FRONT BUMPER NOZZLE COVER RH	Cut	132.00 FL	*28.50 FL
8	1		*FRONT BUMPER NOZZLE PUMP RH	Damaged	618.00 FL	*242.40 FL
9	1		*FRONT BUMPER NOZZLE PUMP HOSE RH	Not Necessary	73.00 FL	*- FL
10	1		*FRONT BUMPER SIGNAL LAMP RH	Mtg Cracked	362.00 FL	*362.00 FL
11	1		*FRONT BUMPER SIGNAL LAMP HOLDER RH	Not Necessary	294.00 FL	*- FL
12	1		*FRONT GRILLE	Not Necessary	680.00 FL	*- FL
13	1		*FRONT GRILLE CHROME	Not Necessary	391.00 FL	*- FL
14	1		*FRONT GRILLE LOGO	Not Necessary	95.00 FL	*- FL
15	1		*FRONT BUMPER UNDER COVER	Not Necessary	300.90 FL	*- FL
16	1		*FRONT FENDER RH	Repair	1,294.00 FL	*- FL
17	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	385.00 FL	*- FL
18	1		*FRONT WHEEL BEARING RH	Not Necessary	284.00 FL	*- FL
19	1		*FRONT WHEEL BEARING HUB RH	Not Necessary	351.00 FL	*- FL
20	1		*FRONT ABSORBER RH	Not Necessary	460.00 FL	*- FL
21	1		*FRONT LOWER ARM RH	Not Necessary	609.00 FL	*- FL
22	1		*FRONT KNUCKLE ARM RH	Not Necessary	1,004.00 FL	*- FL
23	1		*HEAD LAMP RH	Cut / Broken	3,778.00 FL	*2,357.30 FL
24	1		*HEAD LAMP LOWER BRACKET RH	Not Necessary	192.00 FL	*- FL
25	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
26	1		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
27	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
28	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
29	1		*SPORT RIM	Not Necessary	1,000.00 FS	*- FS
30	1		*TYRE	Not Necessary	300.00 FS	*- FS
31	1		*FRONT NO PLATE & GARNISH	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,736.90	4,150.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,827.38	826.04
Total Parts (\$\$)	12,909.52	3,324.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILIATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	500.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	400.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	20.00
5	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	New	250.00	0.00
6	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	250.00	0.00
7	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
8	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			5,600.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >