

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22011889/TPA3Q2**Date:** 28/02/2023REFERENCE

| | | | |
|------------------------------|---------------------------------------|-----------------------------|--------------|
| Handling Insurer: | Allianz Insurance Singapore Pte. Ltd. | Policy No: | SP2002182276 |
| Claimant Vehicle No : | SMK4212S | Insured Vehicle No : | SMU1807T |
| Date of Loss: | 25/11/2022 | Nature of Claim: | TP |
| | | Claim No: | 202222008454 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------|
| Reg No: | SMK4212S | Engine No: | 4J11AC0429 |
| Make & Model: | MINI COOPER, 2.0 CVT (A) | Chassis No: | GF7W0600457 |
| Reg. Date: | 09/04/2019 (Man. Year: 2018) | Odometer: | 81319 km |
| Colour: | Silver | | |
| Engine Capacity: | 1998 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 225/55 R18 | Rear Tyre Size: | 225/55 R18 |
| Front Left Side: | Yokohama 6 mm | Rear Left Side: | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 5,748.00 | 3,923.00 | 1,825.00 | 31.75 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,570.00 | 2,180.00 | 1,390.00 | 38.94 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 9,318.00 | 6,103.00 | 3,215.00 | 34.50 |
| + GST 8.00/8.00% (S\$) | 745.44 | 488.24 | 257.20 | 34.50 |
| Nett Amount (S\$) | 10,063.44 | 6,591.24 | 3,472.20 | 34.50 |
| + Car Rental (4.0 x S\$160.00/day + 7.00% GST) (S\$) | | 684.80 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| Nett Liability (S\$) | | 7,278.04 | | |

INSPECTION

| | | |
|-----------------------------|--------------------------|--|
| Date of Assignment: | 26/11/2022 | CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (ubi) 330 UBI ROAD 3 Singapore 408650 |
| Date Inspected: | 29/11/2022 Inspected At: | |
| Estimated Period of Repair: | 4.0 days | |

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

| | |
|--|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 27 Feb 2023) |
| Parts: M1-SUV | MITSUBISHI OUTLANDER 2.0 CVT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SMK4212S) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *SUNDRIES | Necessary | 50.00 FS | *20.00 FS |
| 2 | 1 | | *RH HEADLAMP ASSY | Cracked | 1,967.00 FS | *1,967.00 FS |
| 3 | 1 | | *FACE ,FR BUMPER | Deformed | 1,023.00 FS | *1,023.00 FS |
| 4 | 1 | | *CLIP,ENG ROOM COVER (25 PCS) | Necessary | 50.00 FS | *50.00 FS |
| 5 | 5 | | *CLIP ,BUMPER | Necessary | 15.00 FS | *15.00 FS |
| 6 | 1 | | *LH SIDE BRACKET ,FR BUMPER | Not Necessary | 18.00 FS | *- FS |
| 7 | 1 | | *RH SIDE BRACKET ,FR BUMPER | Necessary | 18.00 FS | *18.00 FS |
| 8 | 1 | | *RH SIDE GARNISH,FR BUMPER | Cut | 49.00 FS | *49.00 FS |
| 9 | 1 | | *RH UPR GARNISH ,FR BUMPER | Cut | 222.00 FS | *222.00 FS |
| 10 | 1 | | *RH LWR GARNISH ,FR BUMPER | Cut | 113.00 FS | *113.00 FS |
| 11 | 1 | | *RH FOG GARNISH ,FR BUMPER | Deformed | 48.00 FS | *48.00 FS |
| 12 | 1 | | *RH LAMP ASSY ,FOG FR | Not Necessary | 352.00 FS | *- FS |
| 13 | 1 | | *EXTENSION ,FR BUMPER | Not Necessary | 515.00 FS | *- FS |
| 14 | 1 | | *REINFORCEMENT ,FR BUMPER | Not Necessary | 498.00 FS | *- FS |
| 15 | 1 | | *BAR ,FR BUMPER GUARD | Not Necessary | 131.00 FS | *- FS |
| 16 | 1 | | *RH MOULDING ,FR BUMPER | Cut | 102.00 FS | *102.00 FS |
| 17 | 1 | | *RH MOULDING ,FR WHEEL ARCH | Cut | 162.00 FS | *162.00 FS |
| 18 | 1 | | *RH SHIELD ,FR WHEELHOUSE | Not Necessary | 166.00 FS | *- FS |
| 19 | 10 | | *CLIP ,RR BUMPER | Necessary | 30.00 FS | *30.00 FS |
| 20 | 1 | | *TANK ,WINDSHIELD WASHER | Deformed | 88.00 FS | *88.00 FS |
| 21 | 1 | | *SENSOR ,W/SHLD WASHER TANK | Not Necessary | 115.00 FS | *- FS |
| 22 | 4 | | *RIVET ,ENG ROOM COVER | Necessary | 16.00 FS | *16.00 FS |

F=Franchise part. S=SpcNett.

| | | |
|--------------------------|-----------------|-----------------|
| Total Parts (S\$) | 5,748.00 | 3,923.00 |
|--------------------------|-----------------|-----------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|--|----------|--------------------------------|-----------------|
| Labour Items | | | | |
| 1 | TO CARRY OUT DIAGNOSTIC CHECK BY NUT AND CLEAR TROUBLE CODE | New | 280.00 | 280.00 |
| 2 | TO CHECK WIRING AND ELECTRICAL SYSTEM | New | 80.00 | 80.00 |
| 3 | TO REPLACE RH HEADLAMP,FRONT BUMPER ,CLIPS ,BRACKETS ,RH CHROME GARNISH ,RH FOG LAMP & COVER ,EXTENSION BPR ,REINFORCEMENT ,RH BPR & ARCH MLDG,ETC STRAIGHTEN REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS | New | 1,280.00 | 640.00 |
| 4 | SPRAY PAINTING ON RHF ACCIDENT AFFECTED AREAS (FRONT BUMPER ,RHF FENDER) | New | 1,650.00 | 1,100.00 |
| 5 | TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT | New | 180.00 | 0.00 |
| 6 | TO APPLY ANTI -CORROSION ON AFFECTED AREAS | New | 100.00 | 80.00 |
| | | | Gross Labour Cost (S\$) | 3,570.00 |
| | | | | 2,180.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >