

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22011890/AYA3Q2**Date:** 19/04/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002755283
Claimant Vehicle No :	SKH6599C	Insured Vehicle No :	SCX7343C
Date of Loss:	24/11/2022	Nature of Claim:	TP
		Claim No:	202222008434

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH6599C	Engine No:	1NZX816092
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305085532
Reg. Date:	10/02/2009 (Man. Year: 2008)	Odometer:	281646 km
Colour:	Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,165.31	3,548.87	2,616.44	42.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,780.00	1,200.00	40.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,145.31	5,328.87	3,816.44	41.73
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	9,145.31	4,200.00	4,945.31	54.07
+ GST 8.00/8.00% (S\$)	731.62	336.00	395.62	54.07
Nett Amount (S\$)	9,876.93	4,536.00	5,340.93	54.07
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,043.45		

INSPECTION

Date of Assignment:	27/11/2022	Twincar Automotive Pte Ltd - Kaki Bukit (HQ)
Date Inspected:	28/11/2022 Inspected At:	2 KAKI BUKIT AVENUE 2, #01-17 KAKI BUKIT AUTOHUB
Estimated Period of Repair:	6.0 days	Singapore 417921

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2023)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKH6599C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	666.70 FL	*666.70 FL
2	1		*REAR BOOTLID LOGO EMBLEM	Necessary	53.90 FL	*53.90 FL
3	2		*REAR BOOTLID HINGE L/R	Not Necessary	119.00 FL	*- FL
4	1		*REAR BOOTLID MECHANISM LOCK	Damaged	106.40 FL	*106.40 FL
5	1		*REAR BOOTLID MECHANISM LOCK STRIKER	Not Necessary	43.55 FL	*- FL
6	1		*REAR BOOTLID OUTER GARNISH	Cracked	181.70 FL	*181.70 FL
7	2		*REAR BOOTLID RUBBER GUIDE STOPPER L/R	Not Necessary	87.80 FL	*- FL
8	1		*REAR BOOTLID WEATHERSTRIP	Cut	194.20 FL	*194.20 FL
9	1		*REAR BUMPER	Deformed	495.70 FL	*495.70 FL
10	2		*REAR BUMPER BRACKET L/R	Bent	139.80 FL	*139.80 FL
11	2		*REAR BUMPER END SEAL COVER L/R	Not Necessary	111.00 FL	*- FL
12	2		*REAR BUMPER REFLECTOR L/R	Cracked	184.00 FL	*184.00 FL
13	2		*REAR BUMPER SIDE CORNER BRACKET L/R	Not Necessary	79.60 FL	*- FL
14	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	205.60 FL	*205.60 FL
15	1		*REAR CENTER SPONGE	Not Necessary	146.40 FL	*- FL
16	1		*REAR END PANEL	Dented	696.30 FL	*696.30 FL
17	1		*REAR END PANEL INNER TOP GARNISH	Deformed	222.80 FL	*125.00 FL
18	1		*REAR EXHAUST GASKET	Not Necessary	61.10 FL	*- FL
19	3		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	191.70 FL	*- FL
20	1		*REAR EXHAUST SILENCER BOX	Not Necessary	771.10 FL	*- FL
21	2		*REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	Not Necessary	495.80 FL	*- FL
22	1		*REAR LH SPARE TYRE TOP SPONGE	Deformed	190.00 FL	*190.00 FL
23	1		*REAR NUMBER PLATE	Not Necessary	25.00 FL	*- FL
24	2		*REAR NUMBER PLATE LAMP L/R	Not Necessary	130.80 FL	*- FL
25	1		*REAR RH SPARE TYRE TOP SPONGE	Deformed	237.10 FL	*237.10 FL
26	1		*REAR SPARE TYRE INNER TOP CARDBOARD COVER	Torn	172.10 FL	*172.10 FL
27	2		*REAR TAILLAMP BACK RUBBER GASKET L/R	Necessary	122.20 FL	*40.00 FL
28	2		*REAR TAILLAMP L/R	Cracked	760.00 FL	*590.00 FL
29	2		*REAR TAILLAMP PANEL L/R	Repair	462.40 FL	*- FL
30	1		*SET REAR BOOTLID OUTER GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
31	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
32	2		*SET REAR BUMPER END SEAL COVER CLIPS L/R	Not Necessary	40.00 FS	*- FS
33	1		*REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
34	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS

Report was unsubmitted during this print-out.

4/19/23, 1:09 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
35	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
36	2		*SET REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R	Not Necessary	60.00 FS	*- FS
37	1		*REAR NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
38	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	60.00 FS	*20.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					8,003.75	4,618.50
- List Item Discount on L Items 25.00/25.00% (S\$)					1,838.44	1,069.63
Total Parts (S\$)					6,165.31	3,548.87
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	60.00	60.00
2	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	120.00	60.00
3	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,400.00	800.00
4	TO REMOVE AND CHARGE EXHAUST SILENCER BOX WITH PIPE ,RE- ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	120.00	0.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE- ALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	800.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	60.00
Gross Labour Cost (\$\$)			2,980.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >