

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22011892/DYA3Q2**Date:** 20/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070176082
Claimant Vehicle No :	SGM9174X	Insured Vehicle No :	SMW9125P
Date of Loss:	13/11/2022	Nature of Claim:	TP
		Claim No:	8016712595SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGM9174X	Engine No:	3SZ1677038
Make & Model:	TOYOTA RUSH, 1.5 (A)	Chassis No:	J200E0008163
Reg. Date:	31/10/2006 (Man. Year: 2006)	Odometer:	280331 km
Colour:	Grey		
Engine Capacity:	1495 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R16	Rear Tyre Size:	215/65 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,039.10	1,341.65	2,697.45	66.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	950.00	950.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,939.10	2,291.65	3,647.45	61.41
Approved Total (Overridden) (S\$)		1,800.00		
Nett Amount (S\$)	5,939.10	1,800.00	4,139.10	69.69
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
Nett Liability (S\$)		1,980.00		

INSPECTION

Date of Assignment:	28/11/2022	Alfred Auto Services & Supplies (HQ)
Date Inspected:	28/11/2022 Inspected At:	Blk 5035, Ang Mo Kio Ave 3, #01-351, Ang Mo Kio Industrial Park 2
Estimated Period of Repair:	3.0 days	Singapore 569538

Adjuster: BRYAN TANI**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,130.00 F	*981.10 FL
2	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	489.60 F	*- FL
3	1		*FRONT BUMPER TOWING COVER	Not Necessary	105.00 F	*- FL
4	10		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*20.00 FS
5	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	218.00 F	*- FL
6	1		*FRONT RH HEAD LAMP ASSY	Mtg Cracked	998.60 F	*781.10 FL
7	1		*FRONT NO PLATE & BOX	Not Necessary	80.00 F	*- FL
8	1		*FRONT RH FENDER	Repair	699.30 F	*- FL
9	1		*FRONT RH FENDER DUST GARNISH	Not Necessary	198.60 F	*- FL
10	10		*DUST GARNISH CLIPS	Not Necessary	60.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,039.10	1,782.20
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	440.55
Total Parts (\$\$)	4,039.10	1,341.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE WIRING & RENEW PARTS & CHECK ALL WIRE	New	100.00	30.00
2	TO KNOCKING ,STRAIGHTENING ,REPAIR & RENEW ALL ACCIDENT DAMAGED AFFECTED AREA	New	800.00	500.00
3	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED PARTS	New	880.00	400.00
4	TO RUST PROOF ALL ACCIDENT AFFECTED AREA	New	120.00	20.00
Gross Labour Cost (\$\$)			1,900.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >