

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22011893/KYA3Q2**Date:** 12/05/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900142692
Claimant Vehicle No :	SHC5268B	Insured Vehicle No :	SKV2756T
Date of Loss:	24/11/2022	Nature of Claim:	TP
		Claim No:	7946952250SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5268B		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2H00815
Reg. Date:	09/10/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU703092186
Colour:	Metallic Pearl White/Red	Odometer:	185241 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Wanli 5 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Wanli 5 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,116.45	13,719.50	4,396.95	24.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,870.00	1,050.00	8,820.00	89.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	27,986.45	14,769.50	13,216.95	47.23
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	24/11/2022		
Date Inspected:	24/11/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD SUB-ASSY	Repair	983.10 FL	*- FL
2	1		*INSULATOR, HOOD	Serviceable	410.90 FL	*- FL
3	1		*HINGE ASSY, HOOD, LH	Repair	58.90 FL	*- FL
4	1		*HINGE ASSY, HOOD, RH	Repair	58.90 FL	*- FL
5	1		*FENDER SUB-ASSY, FRONT LH	Bent	977.80 FL	*977.80 FL
6	1		*LINER, FRONT FENDER, LH	Torn	210.30 FL	*210.30 FL
7	1		*EMBLEM, SIDE PANEL	Necessary	54.60 FL	*54.60 FL
8	1		*COVER, FRONT BUMPER	Torn	521.00 FL	*521.00 FL
9	1		*MOULDING, FRONT BUMPER SIDE, LH	Missing	95.60 FL	*95.60 FL
10	1		*REINFORCEMENT SUB-ASSY, FRONT BUMPER	Bent	716.60 FL	*716.60 FL
11	1		*REINFORCEMENT, FRONT BUMPER, NO.2	Repair	246.10 FL	*- FL
12	1		*ABSORBER, FRONT BUMPER, LOWER	Cracked	132.70 FL	*132.70 FL
13	1		*ABSORBER, FRONT BUMPER ENERGY	Cracked	80.20 FL	*80.20 FL
14	1		*SUPPORT, FRONT BUMPER SIDE, LH	Distorted	82.30 FL	*82.30 FL
15	1		*COVER SUB-ASSY, ENGINE UNDER, NO.2	Serviceable	241.90 FL	*- FL
16	1		*EXTENSION, FRONT BUMPER, LH	Serviceable	120.10 FL	*- FL
17	1		*EXTENSION, FRONT BUMPER, RH	Serviceable	120.10 FL	*- FL
18	1		*STAY SUB-ASSY, FRONT BUMPER, RH	Serviceable	47.50 FL	*- FL
19	1		*STAY SUB-ASSY, FRONT BUMPER, LH	Serviceable	47.50 FL	*- FL
20	1		*BRACKET, FRONT BUMPER SIDE, LH	Cracked	59.30 FL	*59.30 FL
21	1		*BRACKET, FRONT BUMPER SIDE, RH	Serviceable	59.30 FL	*- FL
22	1		*COVER, FRONT BUMPER HOLE, LH	Missing	30.20 FL	*30.20 FL
23	1		*BRACKET, HEADLAMP, LH	Cracked	34.80 FL	*34.80 FL
24	1		*LAMP ASSY, FOG, LH	Cracked	237.10 FL	*237.10 FL
25	1		*UNIT ASSY, HEADLAMP, LH	Cracked	2,637.60 FL	*2,637.60 FL
26	1		*GRILLE SUB-ASSY, RADIATOR	Distorted	422.50 FL	*422.50 FL
27	1		*EMBLEM ASSY, MOULDING	Necessary	160.50 FL	*160.50 FL
28	1		*GRILLE, RADIATOR, LOWER NO.1	Dented / Distorted	178.60 FL	*178.60 FL
29	1		*EMBLEM ASSY, RADIATOR GRILLE	Necessary	105.80 FL	*105.80 FL
30	1		*CONDENSER ASSY, COOLER	Serviceable	1,783.20 FL	*- FL
31	1		*SUPPORT, RADIATOR UPPER LH	Repair	78.90 FL	*- FL
32	1		*SUPPORT, RADIATOR UPPER RH	Repair	78.90 FL	*- FL
33	1		*SUPPORT SUB-ASSY, RADIATOR, UPPER	Repair	377.10 FL	*- FL
34	1		*SUPPORT SUB-ASSY, RADIATOR, RH	Repair	245.10 FL	*- FL
35	1		*SUPPORT SUB-ASSY, RADIATOR, LH	Repair	245.10 FL	*- FL
36	1		*FRT NUMBER PLATE WITH HOLDER	Serviceable	140.00 FS	*- FS
37	1		*SET BUMPER CLIP FRT	Necessary	95.00 FS	*60.00 FS
38	1		*SET FRONT BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS
39	4		*L RADIATOR COOLANT	Not Necessary	120.00 FS	*- FS
40	1		*HOOD INSULATOR CLIP	Not Necessary	55.00 FS	*- FS
41	1		*ENGINE UNDER COVER CLIP	Not Necessary	60.00 FS	*- FS
42	1		*FRT FENDER LINER CLIP	Necessary	65.00 FS	*65.00 FS
43	1		*BRACE SUB-ASSY, FENDER APRON, LH	Bent	292.10 FL	*292.10 FL
44	1		*WIRE, ENGINE ROOM MAIN	Torn	7,323.90 FL	*7,323.90 FL
45	1		*COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	Dented	3,772.50 FL	*3,772.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	23,948.60	18,251.00
- List Item Discount on L Items 25.00/25.00% (\$)	5,832.15	4,531.50
Total Parts (\$)	18,116.45	13,719.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	4,000.00	500.00
3	TO REMOVE AND REFIT ELECTRICAL WIRING, BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
4	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
5	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT, VACUUM AND CHARGE-IN-GAS	New	380.00	0.00
6	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
8	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	30.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	500.00
10	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
11	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
12	TO REMOVE AND REFIT RADIATOR SUPPORT CROSS-MEMBER AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR	New	380.00	0.00
13	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
Gross Labour Cost (\$\$)			9,870.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >