

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22011896/TNY3Q2**Date:** 13/01/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MJ001139		
Claimant Vehicle No :	SHB3815R	Insured Vehicle No :	SFP1118H		
Date of Loss:	24/11/2022	Nature of Claim:	TP	Claim No:	M2206694

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB3815R	Engine No:	D4FDGU689974
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMHU099992
Reg. Date:	15/12/2017 (Man. Year: 2016)	Odometer:	0 km
Colour:	Yellow		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,949.86	1,099.44	2,850.42	72.17
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,740.00	980.00	760.00	43.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,700.86	2,090.44	3,610.42	63.33
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	5,700.86	1,650.00	4,050.86	71.06
+ GST 7.00/7.00% (S\$)	399.06	115.50	283.56	71.06
Nett Amount (S\$)	6,099.92	1,765.50	4,334.42	71.06

INSPECTION

Date of Assignment:	28/11/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	28/11/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jan 2023)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB3815R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	2,609.80 FL	*- FL
2	2		*BOOTLID HINGE RH / LH	Repair	284.00 FL	*- FL
3	1		*BOOTLID H EMBLEM	Necessary	63.10 FL	*63.10 FL
4	1		*BOOTLID CRDI EMBLEM	Necessary	52.40 FL	*52.40 FL
5	1		*BOOTLID COMFORTDELGRO EMBLEM	Necessary	30.00 F	*30.00 F
6	1		*BOOTLID 65521111 EMBLEM	Necessary	30.00 F	*30.00 F
7	1		*REAR BUMPER	Cracked	553.00 FL	*553.00 FL
8	1		*REAR BUMPER UNDER COVER	Deformed	228.00 FL	*228.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Not Necessary	428.40 FL	*- FL
10	2		*REAR BUMPER REINFORCEMENT BRKT RH / LH	Not Necessary	71.20 FL	*- FL
11	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
12	1		*BOOTLID MOULDING	Cut	85.00 FL	*85.00 FL
13	1		*BOOTLID LOWER GARNISH	Cut	227.90 FL	*227.90 FL
14	1		*REVERSE SENSORS	Not Necessary	135.70 F	*- F
15	1		*BOOTLID I40 EMBLEM	Necessary	67.90 FL	*67.90 FL
Sub Total (S\$)						4,888.40 1,359.30
- List Item Discount on L Items 20.00/20.00% (S\$)						938.54 259.86
Total Parts (S\$)						3,949.86 1,099.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	900.00	420.00
2	SPRAY PAINTING	New	600.00	500.00
3	TUFF KOTE	New	60.00	0.00
4	R/I REVERSE SENSORS	New	120.00	0.00
5	TOWING FEE	New	60.00	60.00
Gross Labour Cost (\$\$)			1,740.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >