



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 630E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COVER, REAR BUMPER	BUCKLED	485.60	485.60
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	BENT	332.70	332.70
1	GUARD, REAR BUMPER, CENTER	DENTED/CUT	374.50	374.50
1	SEAL, REAR BUMPER SIDE, LH	SERVICEABLE	118.30	-
1	SEAL, REAR BUMPER SIDE, RH	SERVICEABLE	118.30	-
1	RETAINER, REAR BUMPER SIDE, RH	SERVICEABLE	132.60	-
1	RETAINER, REAR BUMPER SIDE, LH	SERVICEABLE	132.60	-
1	COVER, REAR BUMPER, LOWER	DENTED	22.00	22.00
1	COVER, DECK TRIM, REAR	SERVICEABLE	126.70	-
1	COVER, FLOOR UNDER, NO.2 (RH)	SERVICEABLE	241.90	-
1	COVER, FLOOR UNDER, NO.1 (LH)	SERVICEABLE	175.10	-
1	COVER, REAR FLOOR (CTR)	MTG CRACKED	229.90	229.90
1	PANEL SUB-ASSY, BODY LOWER BACK	TO REPAIR SEE LABOUR	651.00	-
	LESS 25% DISCOUNT		-785.30	-361.17
			2,355.90	1,083.53
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER SIDE CLIP (SN)	NECESSARY	60.00	60.00
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	85.00	-
1	REAR BUMPER RETAINER CLIP (SN)	NOT NECESSARY	75.00	-
			920.00	60.00
<u>LABOUR</u>				
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	240.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, BODY LOWER BACK.		1,800.00	200.00

Report Ref No. CS/AGI22011904/Kvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,600.00	220.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	50.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	10.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO REMOVE AND REFIT OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			5,300.00	480.00
GRAND TOTAL			8,575.90	1,623.53
RECOMMENDED COST OF REPAIRS				1,623.53

Report Ref No. CS/AGI22011904/Kvy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.