

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011916/KNP3M4**Date:** 10/01/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00093202205

Claimant Vehicle No : SKS3907J **Insured Vehicle No :** GBD2691Y

Date of Loss: 22/11/2022 Nature of Claim: TP Claim No: SNM22D208437/C05/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKS3907J**

Make & Model: TOYOTA CAMRY, 2.4 G (A) Engine No: 2AZC290879

Reg. Date: 12/01/2008 (Man. Year: 2007) Chassis No: ACV403142075

Colour: Metallic Black Odometer: 136342 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/45R17 Rear Tyre Size: 235/45R17

Front Left Side: Pirelli 6 mm Rear Left Side: Goodyear 5 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,319.00	1,489.89	2,829.11	65.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	845.00	715.00	45.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,879.00	2,334.89	3,544.11	60.28
Approved Total (Overridden) (S\$)		1,850.00		
(S\$)	5,879.00	1,850.00	4,029.00	68.53
+ GST 7.00/7.00% (S\$)	411.53	129.50	282.03	68.53
Nett Amount (S\$)	6,290.53	1,979.50	4,311.03	68.53

INSPECTION

Date of Assignment: 25/11/2022

Date Inspected: 29/11/2022 Inspected At: Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
Autopoint
Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2023)
Parts:	143	TOYOTA CAMRY 2.4 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS3907J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY LH	Serviceable	2,800.75 FL	*- FL
2	1		*FRONT BUMPER	Mtg Cracked	823.20 FL	*823.20 FL
3	12		*FRONT BUMPER CLIPS	Necessary	57.60 FL	*57.60 FL
4	1		*FRONT BUMPER TOP RUBBER	Serviceable	137.80 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	91.60 FL	*91.60 FL
6	1		*FOGLAMP LH	Serviceable	236.90 FL	*- FL
7	1		*FOG LAMP COVER RH	Serviceable	75.80 FL	*- FL
8	1		*FRONT FENDER LH	Bent	812.75 FL	*812.75 FL
9	1		*FRONT FENDER SIGNAL LAMP LH	Serviceable	78.40 FL	*- FL
10	3		*FRONT FENDER TOP GARNISH CLIPS	Not Necessary	11.10 FL	*- FL
11	1		*FRONT FENDER COWLING RH	Cracked	175.77 FL	*175.77 FL
12	8		*FRONT FENDER COWLING CLIPS	Necessary	25.60 FL	*25.60 FL
13	1		*FRONT WHEEL HUB LH	Not Necessary	241.70 FL	*- FL
14	1		*FRONT WHEEL BEARING LH	Not Necessary	189.70 FL	*- FL
15	1		*TYRE LHF (235/45 R17) (NPA)	Serviceable	0.00 FS	*- FS
16	1		*SPORT RIM LHF (NPA)	Serviceable	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,758.67	1,986.52
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,439.67	496.63
Total Parts (\$\$)	4,319.00	1,489.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	15.00
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	80.00	0.00
3	TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE	New	80.00	0.00
4	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
5	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR FRONT DOOR LH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME	New	600.00	400.00
6	TO SPRAY FRONT BUMPER, FRONT FENDER LH, FRONT DOOR LH	New	700.00	400.00
Gross Labour Cost (S\$)			1,560.00	845.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >