3/9/23, 12:14 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22011917/UYA3Q2

09/03/2023 Date:

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700032468 **Claimant Vehicle** 

SMX8651M Insured Vehicle No: SGC8818G No:

Date of Loss: 14/11/2022 Nature of Claim: TP Claim No: 9639737648SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMX8651M

Make & Model: HYUNDAI CN7 AVANTE, 1.6 DOHC CVT S (A) Engine No: G4FMLU209550

Reg. Date: 03/02/2021 (Man. Year: 2020) Chassis No: KMHLN41ETMU112015

Colour: Odometer: 20043 km Red

**Engine Capacity:** 1598 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 205/55 R16 Rear Tyre Size: Front Left Side: Hankook 7 mm Rear Left Side: Hankook 7 mm Front Right Side: Hankook 7 mm Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,589.36	520.00	2,069.36	79.92
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,115.00	1,070.00	1,045.00	49.41
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	4,704.36	1,590.00	3,114.36	66.20
	+ GST 7.00/7.00% (S\$)	329.31	111.30	218.01	66.20
	Nett Amount (S\$)	5,033.67	1,701.30	3,332.37	66.20
	+ Loss of Use (3.0 x	S\$60.00/day) (S\$)	180.00		
	+ Do	c/Search Fee (S\$)	2.00		
		Nett Liability (S\$)	1,883.30		

**INSPECTION** 

Date Inspected:

Date of Assignment: 01/12/2022

> Specialists Motor Pte Ltd (HQ) 01/12/2022 Inspected At:

Blk 3018A Ubi Road 1, #01-24/25/26

Singapore 408711

Estimated Period of Repair: 3.0 days

MARCUS CHUA Adjuster: Manager: Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BOOT COVER	Repair	2,023.20 FL	*- FL	
2	1		*REAR BOOT COVER EMBLEM (AVANTE)	Necessary	41.20 FL	*41.20 FL	
3	1		*REAR BOOT COVER EMBLEM (S)	Necessary	58.00 FL	*58.00 FL	
4	1		*REAR BUMPER FASCIA	Dented	470.80 FL	*470.80 FL	
5	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL	
6	2		*REAR BUMPER SIDE RETAINER L&RH	Not Necessary	76.00 FL	*- FL	
7	1		*REAR BUMPER SENSOR	Serviceable	380.00 FS	*-FS	
8	1		*REAR NUMBER PLATE	Bent	50.00 FS	*40.00 FS	
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.	_			
				Sub Total (S\$)	3,129.20	640.00	
	- List Item Discount on L Items 20.00/20.00% (S\$)					120.00	
				Total Parts (S\$)	2,589.36	520.00	
	Report was unsubmitted during this print-out.						

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	CUT OUT ,RENEW KNOCKING & WELDING REAR BOOT COVER ,REAR END PANEL,REMOVE & REINSTALL ALL DAMAGE PARTS & RE-ALIGN BODY	New	880.00	500.00
2	TUFF-KOTE ON DAMAGE PARTS	New	40.00	0.00
3	SPRAY PAINTING ON DAMAGE PARTS	New	1,080.00	500.00
4	REMOVE & REFIX REAR BUMPER SENSOR	New	80.00	50.00
5	CHECK ALL LIGHTING AFTER REPAIRS	New	35.00	20.00
	Gross Labo	ur Cost (S\$)	2,115.00	1,070.00
	Report was unsubmitted during thi	s print-out.		

< END OF ESTIMATES >