

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22011920/UNP3Q2**Date:** 12/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00174062202
<b>Claimant Vehicle No :</b>	SKM8886J	<b>Insured Vehicle No :</b>	SJH3787H
Date of Loss:	24/11/2022	Nature of Claim:	TP
		Claim No:	SNM22D208508/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKM8886J</b>	Engine No:	27492030407779
Make & Model:	MERCEDES-BENZ E250, 1.8 (A)	Chassis No:	WDD2120362B205809
Reg. Date:	27/01/2016 (Man. Year: 2015)	Odometer:	48962 km
Colour:	Red		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,325.50	6,462.79	1,862.71	22.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	480.00	1,320.00	73.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,125.50</b>	<b>6,942.79</b>	<b>3,182.71</b>	<b>31.43</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,500.00</b>		
<b>(S\$)</b>	10,125.50	5,500.00	4,625.50	45.68
<b>+ GST 7.00/7.00% (S\$)</b>	708.79	385.00	323.79	45.68
<b>Nett Amount (S\$)</b>	<b>10,834.29</b>	<b>5,885.00</b>	<b>4,949.29</b>	<b>45.68</b>

**INSPECTION**

Date of Assignment:	28/11/2022	
Date Inspected:	05/12/2022	Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	2.0 days	

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 12 Dec 2022)
<b>Parts:</b> 143	MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SKM8886J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S HEADLAMP	Cracked	5,688.00 FL	*5,024.32 FL
2	1		*O/S HEADLAMP LOWER BRACKET	Not Necessary	447.00 FL	*- FL
3	1		*FRONT BUMPER	Cut / Deformed	1,975.00 FL	*1,753.22 FL
4	1		*O/S FRONT BUMPER SIDE RETAINER	Not Necessary	185.00 FL	*- FL
5	1		*O/S FRONT BUMPER SENSOR	Not Necessary	296.00 FL	*- FL
6	6		*FRONT BUMPER SENSOR RING	Not Necessary	108.00 FL	*- FL
7	6		*FRONT BUMPER SENSOR BRACKET	Necessary	270.00 FL	*270.00 FL
8	1		*O/S FRONT BUMPER AIR GRILLE	Not Necessary	126.00 FL	*- FL
9	1		*SET FRONT BUMPER CLIP	Necessary	60.00 FS	*60.00 FS
10	1		*SET FRONT BUMPER RIVET	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,235.00</b>	<b>7,167.54</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	909.50	704.75
<b>Total Parts (\$\$)</b>	<b>8,325.50</b>	<b>6,462.79</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO FOCUS HEADLAMP & WIRING	New	50.00	20.00
2	TO RESET CLEARANCE SONAR USING DIAGNOSTIC SCANNER }	New	250.00	60.00
3	TO PROGRAM AND RECODE HEADLAMP MODULE }	New	400.00	0.00
4	TO REPAIR INNER PANEL ,ACCIDENT DAMAGE AREA, REPLACEMENT OF PARTS AND ALIGN THE SAME	New	500.00	200.00
5	TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA	New	600.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,800.00</b>	<b>480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >