

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988**Our File No:** CS/EGI22011922/GNY3E2**Date:** 08/05/2023**REFERENCE**

Insured/Claimant:	Cheng Fong Enterprises (S) Pte Ltd	Policy No:	DMCG22000886
Date of Loss:	24/11/2022	Nature of Claim:	OD
		Claim No:	CDMCG22002542

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE5732M		
Make & Model:	TOYOTA DYNA 150 MANUAL, 3.0 D (M)	Engine No:	1KD2573991
Reg. Date:	20/01/2016 (Man. Year: 2015)	Chassis No:	JTFAT35YX0K205588
Colour:	Silver	Odometer:	282988 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$46,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12
Front Left Side:	Triangle 6 mm	Rear Left Side:	APLUS 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	APLUS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,063.00	5,247.00	2,816.00	34.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	1,420.00	240.00	14.46
Paintwork Labour	780.00	780.00	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,503.00	7,447.00	3,056.00	29.10
- Excess (S\$)	0.00	750.00	-750.00	
(S\$)	10,503.00	6,697.00	3,806.00	36.24
+ GST 7.00/8.00% (S\$)	735.21	535.76	199.45	27.13
Nett Amount (S\$)	11,238.21	7,232.76	4,005.45	35.64

INSPECTION

Date of Assignment:	28/11/2022	Present Location:	Vin's Motor Pte Ltd (Sin Ming)
Date Inspected:	29/11/2022	Inspected At:	Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	8.0 days		

Adjuster: XING GUO QIANG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 May 2023)	
Parts:	N/A	TOYOTA DYNA 150 MANUAL 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE5732M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WIPER PANEL (WCP)	Buckled	160.00 F	*160.00 F
2	1		*FRONT WIPER PANEL LOWER PROTECTOR (WCP)	Cracked	180.00 F	*180.00 F
3	1		*FRONT RH WIPER ARM (WCP)	Cut	80.00 F	*80.00 F
4	1		*FRONT LH WIPER ARM (WCP)	Not Necessary	80.00 F	*- F
5	1		*FRONT WIPER LINKAGE (WCP)	Bent	210.00 F	*210.00 F
6	1		*FRONT WIPER MOTOR (WCP)	Not Necessary	500.00 F	*- F
7	2		*WIPER NOZZIE (WCP)	Bent	60.00 F	*60.00 F
8	1		*FRONT PANEL-OUTER (WCP)	Buckled	720.00 F	*720.00 F
9	1		*FRONT GRILLE (WCP)	Cracked	280.00 F	*280.00 F
10	1		*FRONT GRILLE EMBLEM (WCP)	Necessary	40.00 F	*40.00 F
11	1		*FRONT GRILLE RUBBER (WCP)	Necessary	20.00 F	*20.00 F
12	1		*RH TOP CORNER PANEL (WCP)	Deformed	80.00 F	*80.00 F
13	1		*RH LOWER CORNER PANEL (WCP)	Not Necessary	120.00 F	*- F
14	1		*RH CORNER PANEL LOWER PROTECTOR (WCP)	Cut	60.00 F	*60.00 F
15	1		*RH CORNER PANEL RETAINER (WCP)	Not Necessary	10.00 F	*- F
16	1		*RH HEADLAMP (WCP)	Distorted	400.00 F	*400.00 F
17	1		*LH HEADLAMP (WCP)	Broken	400.00 F	*400.00 F
18	1		*FRONT BUMPER (WCP)	Distorted	240.00 F	*240.00 F
19	1		*FRONT WINDSCREEN GLASS RUBBER (WCP)	Necessary	180.00 F	*180.00 F
20	1		*AIRCON BLOWER UNIT (WCP)	Broken	730.00 F	*730.00 F
21	1		*FRONT RH DOOR STEP GARNISH (WCP)	Broken	170.00 F	*170.00 F
22	1		*FRONT LH DOOR STEP GARNISH (WCP)	Not Necessary	170.00 F	*- F
23	1		*FRONT CABIN BAR (WCP)	Not Necessary	410.00 F	*- F
24	1		*POWER STEERING PUMP (WCP)	Not Necessary	920.00 F	*- F
25	1		*FRONT BUMPER LH BRACKET MEMBER (WCP)	Not Necessary	90.00 F	*- F

Report was unsubmitted during this print-out.

5/8/23, 3:08 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
26	1		*CABIN MOUNTING BRACKET (WCP)	Not Necessary	260.00 F	*- F	
27	1		*FRONT NO.PLATE	Cut	40.00 FS	*40.00 FS	
28	1		*ERP BRACKET	Necessary	26.00 FS	*26.00 FS	
<u>Supplementary #1</u>							
29	1		*FRONT PANEL - INNER (WCP)	Dented	700.00 F	*700.00 F	
F=Franchise part. S=SpcNett.							
					Sub Total (S\$)	7,336.00	4,776.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	727.00	471.00
					Total Parts (S\$)	8,063.00	5,247.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO SPRAY PAINTING	New	780.00	780.00
<u>Labour Items</u>				
2	TO REMOVE AND REFIX FRONT WINDSCREEN	New	180.00	120.00
3	TO REPAIR DAMAGES	New	780.00	600.00
<u>Supplementary #2</u>				
<u>Labour Items</u>				
4	REPAIR FRONT CABIN BAR,POWER STEERING PUMP, BUMPER LH BRACKET MEMBER AND CABIN MOUNTING BRACKET	New	700.00	700.00
Gross Labour Cost (\$\$)			2,440.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >