

Vehicle Damage Assessment Report for [GBE5732M]

Estimate Created: 01/05/2023 15:38 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 01/05/2023 15:57 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number	CDMCG22002542
Claim Type	OD		
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number	

Vehicle Information

Brand	Toyota	Model	Hiace
Engine Type			
License Plate Number	GBE5732M	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- VEHICLE MAKE AND MODEL: TOYOTA DYNA	Insurlogic 4 (01/05/2023 15:57)
- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK: CONCLUDED THE COST OF REPAIR AT \$7,447.00 WITH 5 WORKING DAYS	Insurlogic 4 (01/05/2023 15:57)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Front wiper panel		1	160.00	10.00 %	176.00
Front wiper panel lower protector		1	180.00	10.00 %	198.00
RH front wiper arm		1	80.00	10.00 %	88.00
Front wiper linkage		1	210.00	10.00 %	231.00
Wiper nozzle		1	60.00	10.00 %	66.00
Front panel - outer		1	720.00	10.00 %	792.00
Front grille		1	280.00	10.00 %	308.00
Front grille emblem		1	40.00	10.00 %	44.00
Front grille rubber		1	20.00	10.00 %	22.00
RH top corner panel		1	80.00	10.00 %	88.00
RH corner panel lower protector		1	60.00	10.00 %	66.00
RH headlamp		1	400.00	10.00 %	440.00
LH headlamp		1	400.00	10.00 %	440.00
Front windscreen glass rubber		1	180.00	10.00 %	198.00
Aircon blower unit		1	730.00	10.00 %	803.00
RH front door step garnish		1	170.00	10.00 %	187.00
Front panel - inner		1	700.00	10.00 %	770.00
Front bumper		1	240.00	10.00 %	264.00

Parts Subtotal 5,181.00

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Front number plate		1.0	40.00	0.00 %	40.00
ERP bracket		1.0	26.00	0.00 %	26.00

Materials Subtotal 66.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
To remove and refix front windscreen	RnR	120.00	0.00 %	120.00
Panel beating	RnR	600.00	0.00 %	600.00
Repair front cabin bar, power steering pump, bumper LH bracket member and cabin mounting bracket.	RnR	700.00	0.00 %	700.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	780.00	0.00 %	780.00
Labor Rate	S\$ 50 / Hour			
			General Labor Subtotal	1,420.00
			Paint Labor Subtotal	780.00
			Labor Subtotal	2,200.00

Summary

Repair Cost	7,447.00
Discount(0 %)	(0.00)
	7,447.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	7,447.00