

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22011933/Kwp3m4 8 SHENTON WAY #24-01 AXA TOWER 03/01/2023 Date: SINGAPORE 068811 ATTN: ANG YVONNE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SLA 8076G** GBD 2064H Veh. Inspected Policy No. GA617996 Coverage (\$) 0.00 Claim No. S2M04F1D Excess (\$) 0.00 ANG YVONNE **Assign Date** 28/11/2022 Assign From **Vehicle Particulars & Condition** 2. TOYOTA DYNA (M) Make & Model 2982 c.c HIDDEN 2014 Engine No. Year of Reg. JTFAT35Y30K203195 WHITE Chassis No. Colour Odometer 366942 KM Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195 R15X8 KOYOTE 9 mm KOYOTE L/H Front Tyre 195 R15X8 9 mm 155 R12X8 (D) ARIVO R/H Rear Tyre 7/7 mm 155 R12X8 (D) **ARIVO** 7/7 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. 5. **General Information** 14/11/2022 05/12/2022 ( 10:12 AM ) Inspect Date / Time Accident Date JL CAR AND TRUCK SERVICE PTE LTD Survey held at 60 JALAN LAM HUAT, #02-45, CARROS CENTRE, SINGAPORE 737869 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

Report Ref No. CS3/ASM22011933/Kwp3m4

**Estimate Days of Repair** 

**Inspected By** 

5b.

KONG SENG CHEONG

**Licensed Appraiser** 

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

4 Working Days