

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Report Ref : TP22040078

Date: 22 JUN 2022

Tneoh Yunn Chung
c/o Loh & Lee Motor Workshop
Blk 5 #01-37
Pioneer Road North
Singapore 628458

THIRD PARTY SURVEY ACCIDENT OCCURED ON 02 APR 2022

Workshop Name and Address

Loh & Lee Motor Workshop
Blk 5 #01-37
Pioneer Road North
Singapore 628458

As per your instruction dated 08 APR 2022
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

with regard to the above matter.
SMX2897K

1. VEHICLE PARTICULARS

Registration No : SMX2897K
Model : HONDA SHUTTLE HYBRID 1.5
Year / Capacity : Jan 2021 / 1496 cc
Chassis No : GP72117498

Engine No : LEB7151359
Mileage : 047 731 km
Colour : Metallic Blue

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	215/60/R16	Michelin	9.00 mm	Sport
REAR O/S :	215/60/R16	Michelin	9.00 mm	Sport
FRONT N/S :	215/60/R16	Michelin	9.00 mm	Sport
REAR N/S :	215/60/R16	Michelin	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the front side portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 06 working days to complete
5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SMX2897K

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>List Items</u>				
1 pc	Front bumper <i>very cut</i>	bent	\$ 1,378.00	\$ 1,378.00 <i>1050-w</i>
1 pc	Front bumper side retainer <i>SV</i>	bent	\$ 50.00	\$ 50.00 <i>X</i>
1 pc	Front bumper bracket <i>W</i>	bent	\$ 96.60	\$ 96.60 <i>X</i>
10 pcs	Front bumper clips <i>SV W</i>	necessary	\$ 80.00	\$ 80.00 <i>X 301-</i>
1 pc	Headlamp assembly <i>SV</i>	Distorted	\$ 2,151.60	\$ 2,151.60 <i>X</i>
1 pc	Front fender <i>SV</i>	dented	\$ 725.00	\$ 725.00 <i>X</i>
1 pc	Head lamp lower bracket <i>W</i>	cracked	\$ 95.00	\$ 95.00 <i>X</i>
Parts Sub-Total			\$ 4,576.20	\$ 4,576.20
Discount 20.00%			\$ 915.24	\$ 915.24
			\$ 3,660.96	\$ 3,660.96

Vehicle Number : SMX2897K

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>Special Nett Items</u>				
1 pc	Front tyre (sport) <i>SV</i>	damaged	\$ 350.00	\$ 320.00 <i>X</i>
1 pc	Front wheel rim (sport) <i>Nett WH</i>	damaged	\$ 600.00	\$ 600.00 <i>X</i>
Special Nett Sub-Total			\$ 950.00	\$ 920.00
Spare Parts Total			\$ 4,610.96	\$ 4,580.96

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Spare Parts Total c/f	\$ 4,610.96	\$ 4,580.96
1	To check and reconnect snap wiring	\$ 180.00	\$ 150.00 <i>HN</i>
2	To tuff coat affected areas	\$ 180.00	\$ 150.00 <i>20/-</i>
3	To remove and refix interior upholstery	\$ 180.00	\$ 150.00 <i>HN</i>
4	To respray affected areas	\$ 1,400.00	\$ 1,200.00 <i>400/-</i>
5	To check and adjust computer wheel alignment (before and after)	\$ 180.00	\$ 150.00 <i>HN</i>
6	To renew damaged parts, straighten and repair front chassis member front RH door and aligned all parts	\$ 1,800.00	\$ 1,600.00 <i>400/-</i>
7	To apply paint coating protection	\$ 650.00	\$ 650.00 <i>HN</i>
	Total	\$ 9,180.96	\$ 8,630.96

The repairer has agreed to undertake the repair under Sum Basis. We have further adjusted the amount to a Sum Repair of :

\$ 7,350.00

Fong Kok Heng
Fong Kok Heng
Qualified Appraiser



820/- P/P

3 & 4 days.

1684.00
4/5 1300/-

** LTA and SG car mat in liberty documents.
After 1 yr photos by liberty show parts not changed.*

HN - Parts without photos to show damage.

*MV 100K
BTA 47.4K
52.6K.*

*Year of Mnu - 2020
Registration - Jan 2021.*

羅 及 李 摩 哆
LOH & LEE MOTOR WORKSHOP

Business Registration No. 223943 / OOE

Block 5, Pioneer Road North, #01-37, Singapore 628458.

Tel: 268 0909 Pager: 9404 0172 Res: 566 1714

本號修理引擎・打嗎呷和噴漆等。

We Repair Motor Vehicle's Engine, Knocking Panel & Spraying.

TNEOH YUNN CHUNG
BLK 448 JURONG WEST ST 42
#12-234
SINGAPORE 640448

DATE: 22/06/22

DEAR SIRs

ACCIDENT DATE: 02/04/22
FINAL REPAIR BILL TO SMX 2897 K

LUMP SUM REPAIRS RECOMMENDED
BY THE SURVEYOR-----\$ 7,350.00

DOLLARS: SEVEN THOUSAND, THREE HUNDRED AND FIFTY ONLY