

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011944/AVP3E2**Date:** 08/03/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00008142202

**Claimant Vehicle
No :** GBC860U**Insured Vehicle
No :** SJK1904J

Date of Loss: 26/11/2022

Nature of Claim: TP

Claim
No: SNM22D208532/C02/TOHHSDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBC860U**Make & Model: NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD
Turbo (A)

Engine No: ZD30277255K

Reg. Date: 15/04/2011 (Man. Year: 2011)

Chassis No: JN1SC2F24Z0801828

Colour: Silver

Odometer: 339824 km

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 165 R13C

Front Left Side: Tourador 6 mm

Rear Left Side: Tourador 6 mm

Front Right Side: Tourador 6 mm

Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,018.02	4,914.80	1,103.22	18.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	1,930.00	1,630.00	45.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,578.02	6,844.80	2,733.22	28.54
Approved Total (Overridden) (S\$)		5,400.00		
Nett Amount (S\$)	9,578.02	5,400.00	4,178.02	43.62

INSPECTION

Date of Assignment: 29/11/2022

Date Inspected: 29/11/2022 Inspected At:

Automobile Hub Enterprise
1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI
BUKIT
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Mar 2023)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD Turbo (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC860U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	797.10 FL	*797.10 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	545.20 FL	*545.20 FL
3	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	78.80 FL	*- FL
4	1		*FRONT GRILLE	Cracked	469.40 FL	*469.40 FL
5	1		*FRONT GRILLE LOGO	Necessary	86.40 FL	*86.40 FL
6	1		*FRONT PANEL	Dented	1,412.10 FL	*1,412.10 FL
7	1		*CABSTAR WORDING	Necessary	78.50 FL	*78.50 FL
8	1		*FRONT CORNER PANEL	Not Necessary	784.40 FL	*- FL
9	1		*FRONT WIPER PANEL	Dented	553.60 FL	*553.60 FL
10	1		*AIR CON BLOWER	Cracked	1,143.80 FL	*1,143.80 FL
11	1		*FRONT WINDSCREEN MOULDING	Necessary	185.90 FL	*185.90 FL
12	1		*FRONT WING MIRROR COVER	Not Necessary	191.80 FL	*- FL
13	1		*FRONT WIPER ARM	Not Necessary	170.80 FL	*- FL
14	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
15	1		*FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
16	1		*FRONT PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
17	1		*FRONT WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,667.80	5,442.00
- List Item Discount on L Items 10.00/10.00% (S\$)	649.78	527.20
Total Parts (S\$)	6,018.02	4,914.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	800.00
2	SPRAY PAINTING	New	1,200.00	600.00
3	TO APPLY TUFF COAT	New	150.00	40.00
4	TO REMOVE FRONT WINDSCREEN	New	180.00	120.00
5	TO REMOVE DASHBOARD	New	350.00	220.00
6	TO REMOVE AIR CON SYSTEM & TO TOP UP AIR CON GAS	New	180.00	120.00
7	WIRING	New	100.00	30.00
Gross Labour Cost (S\$)			3,560.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >