

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22011946/TVY3Q2**Date:** 05/12/2022**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MP005301		
Claimant Vehicle No :	SHA3909J	Insured Vehicle No :	SMU2845B		
Date of Loss:	26/11/2022	Nature of Claim:	TP	Claim No:	M2206743

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA3909J	Engine No:	1814TZXS321037339
Make & Model:	BYD ALL-NEW E6, 2.0 (A)	Chassis No:	LC0CE4DC8N0011514
Reg. Date:	31/05/2022 (Man. Year: 2022)	Odometer:	3971 km
Colour:	Blue		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	CHAO YANG 6 mm	Rear Left Side:	CHAO YANG 6 mm
Front Right Side:	CHAO YANG 6 mm	Rear Right Side:	CHAO YANG 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,119.60	2,101.98	17.62	0.83
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	850.00	680.00	170.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,980.60	2,792.98	187.62	6.29
+ GST 7.00/7.00% (S\$)	208.64	195.51	13.13	6.29
Nett Amount (S\$)	3,189.24	2,988.49	200.75	6.29

INSPECTION

Date of Assignment:	28/11/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	29/11/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2022)
Parts:	143	BYD ALL-NEW E6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA3909J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Deformed	2,013.75 FL	*2,013.75 FL
2	1		*REAR BUMPER MOULDING	Deformed	528.75 FL	*528.72 FL
3	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
4	1		*REAR BUMPER MAT	Deformed	50.00 F	*50.00 F
5	1		*REAR BUMPER LINE STICKER	Necessary	18.00 F	*18.00 F
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	2,632.50 2,610.47
					- List Item Discount on L Items 20.00/20.00% (\$\$)	512.90 508.49
					Total Parts (\$\$)	2,119.60 2,101.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	500.00	400.00
2	SPRAYPAINT	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	50.00	30.00
Gross Labour Cost (\$\$)			850.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >