

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	INCOME INSURAN	ICE LTD		Ref:	CS3/INC22011948/Rny3m4
	75 BRAS BASAH R		Date:	06/12/2022	
	ATTN: HELENA TA	١N		Code:	INC
1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SKV 546X	Veh. Inspected		SND 7361A
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1199085-001	Excess (\$)		0.00
	Assign From	ANNIE KOH	Assign Date		29/11/2022
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA COROLLA HYBRID SPORT ASCENT 1.8	c.c		1798
	Engine No.	HIDDEN	Year of Reg.		2022
	Chassis No.	JTDBB3BE00J030378	Colour		BLACK
	Odometer	36052 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/65 R15	BRIDGESTONE		6 mm
	L/H Front Tyre	195/65 R15	BRIDGESTONE		6 mm
	R/H Rear Tyre	195/65 R15	BRIDGESTONE		6 mm
	L/H Rear Tyre	195/65 R15	BRIDGESTONE		6 mm
4. Description of Damages					
	THE VEHICLE SUS	IICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.			
5.	General Information				
	Accident Date	04/11/2022	Inspect Date / 1	Time	29/11/2022 ( 04:15 PM )
	Survey held at	GOLD AUTOWORKS PTE LTD			
		48 TOH GUAN ROAD EAST #01-119 ENTERPRISE HUB SINGAPORE 608586			
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/INC22011948/Rny3m4

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**