

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22011952/RNY3Q2**Date:** 19/01/2023**REFERENCE**

Insured/Claimant:	NG JOO LIANG	Policy No:	SP2001964206	
Date of Loss:	28/11/2022	Nature of Claim:	OD	Claim No: 202222008464

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM6871R	Engine No:	1ZR0D97694
Make & Model:	TOYOTA COROLLA, 1.5 (A)	Chassis No:	MR053REH604598141
Reg. Date:	10/07/2019 (Man. Year: 2019)	Odometer:	43780 km
Colour:	Brown		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$94,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,141.90	11,458.40	4,683.50	29.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,035.68	6,185.04	5,850.64	48.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	28,177.58	17,643.44	10,534.14	37.38
+ GST 7.00/7.00% (\$\$)	1,972.43	1,235.04	737.39	37.38
Nett Amount (\$\$)	30,150.01	18,878.48	11,271.53	37.38

INSPECTION

Date of Assignment:	29/11/2022	
Date Inspected:	30/11/2022	Inspected At: BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2023)
Parts:	143	TOYOTA COROLLA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM6871R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*CAR COATING	Not Necessary	800.00 FS	*- FS
3	1		*COVER ,FR BUMPER ,L	Deformed	576.20 FS	*576.20 FS
4	10		*PIECE ,RR BUMPER	Necessary	45.00 FS	*45.00 FS
5	1		*SUPPORT ,FR BUMPER S	Necessary	73.70 FS	*73.70 FS
6	1		*SUPPORT ,FR BUMPER S	Not Necessary	73.70 FS	*- FS
7	2		*CLIP	Necessary	5.60 FS	*5.60 FS
8	2		*RETAINER ,FR FENDER	Necessary	18.80 FS	*18.80 FS
9	1		*FENDER SUB-ASSY ,FR	Bent	982.90 FS	*982.90 FS
10	1		*PROTECTOR ,FR FENDER	Not Necessary	108.70 FS	*- FS
11	1		*LINER ,FR FENDER ,RH	Not Necessary	226.60 FS	*- FS
12	10		*GROMMET	Necessary	27.00 FS	*27.00 FS
13	1		*PANEL SUB-ASSY ,DOOR	Bent	1,359.30 FS	*1,359.30 FS
14	1		*TAPE ,BLACK OUT,NO	Necessary	52.00 FS	*52.00 FS
15	10		*RIVET	Necessary	18.00 FS	*18.00 FS
16	10		*RIVET	Necessary	22.00 FS	*22.00 FS
17	1		*CHECK ASSY ,FR DOOR	Not Necessary	199.40 FS	*- FS
18	1		*HINGE ASSY ,FR DOOR	Not Necessary	105.50 FS	*- FS
19	1		*HINGE ASSY ,FR DOOR	Not Necessary	120.00 FS	*- FS
20	1		*PLATE ,LUGGAGE COMPT	Necessary	38.50 FS	*38.50 FS
21	1		*HEADLAMP ASSY ,RH	Scratched	4,296.20 FS	*4,296.20 FS
22	1		*WHEEL DISC	Scratched	2,368.50 FS	*2,368.50 FS
23	1		*BEARING ,RADIAL BALL	Not Necessary	180.60 FS	*- FS
24	1		*HUB SUB-ASSY ,FR	Not Necessary	283.10 FS	*- FS
25	1		*NUT ,LOCK	Not Necessary	7.90 FS	*- FS
26	1		*END SUB-ASSY ,TIE	Not Necessary	202.30 FS	*- FS
27	1		*KNUCKLE STEERING ,R	Not Necessary	679.30 FS	*- FS
28	1		*JOINT ASSY ,LWR BALL	Not Necessary	257.80 FS	*- FS
29	1		*ARM SUB-ASSY ,SUSPEN	Not Necessary	794.30 FS	*- FS
30	1		*ABSORBER ASSY ,SHOCK	Not Necessary	475.80 FS	*- FS
31	1		*MIRROR ASSY ,OUTER R	Cut	1,360.50 FS	*1,360.50 FS
32	1		*COVER ,OUTER MIRROR	Repair	118.50 FS	*- FS
33	1		*MOULDING ASSY ,FR DO	Necessary	164.20 FS	*164.20 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					16,141.90	11,458.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SUPPLY SEALANT	New	100.00	100.00
2	REPLACE AND REFOCUS HEADLAMP	New	134.64	134.64
3	REMOVE AND TRANSFER DOOR COMPONENTS ONTO NEW DOOR	New	396.00	396.00
4	CHECK WIRING AND CONDUCT WATER TEST	New	134.64	0.00
5	TO RESET ECU AND REPROGRAMME	New	198.00	198.00
6	TO CONDUCT FULL WHEEL ALIGNMENT	New	198.00	198.00
7	REPLACE RH FRONT SUSPENSION	New	1,584.00	0.00
8	REPLACE RIM AND WHEEL BALANCING	New	158.40	158.40
9	SUPPLY RH FRONT TYRE	New	580.00	0.00
10	REPLACE ACC DAMAGED PARTS	New	3,960.00	2,376.00
11	RESPRAY ACC AFFECTED AREAS	New	4,592.00	2,624.00
Gross Labour Cost (S\$)			12,035.68	6,185.04

Report was unsubmitted during this print-out.

< END OF ESTIMATES >