

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22011953/AWY3Q2**Date:** 27/03/2023REFERENCE

| | | | | | |
|------------------------------|----------------------|-----------------------------|----------|-----------|-----|
| Handling Insurer: | HL Assurance Pte Ltd | Policy No: | MP315196 | | |
| Claimant Vehicle No : | SNC8794H | Insured Vehicle No : | SMG367B | | |
| Date of Loss: | 27/11/2022 | Nature of Claim: | TP | Claim No: | TBA |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SNC8794H | Engine No: | 28291480476991 |
| Make & Model: | MERCEDES-BENZ CLA180, 1.6 (A) | Chassis No: | W1K1183842N166101 |
| Reg. Date: | 23/11/2021 (Man. Year: 2020) | Odometer: | 15063 km |
| Colour: | White | | |
| Engine Capacity: | 1332 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 225/45 R18 | Rear Tyre Size: | 225/45 R18 |
| Front Left Side: | Continental 6 mm | Rear Left Side: | Continental 6 mm |
| Front Right Side: | Continental 6 mm | Rear Right Side: | Continental 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 15,281.50 | 8,381.20 | 6,900.30 | 45.15 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,830.00 | 1,020.00 | 1,810.00 | 63.96 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 18,111.50 | 9,401.20 | 8,710.30 | 48.09 |
| Approved Total (Overridden) (S\$) | | 7,500.00 | | |
| Nett Amount (S\$) | 18,111.50 | 7,500.00 | 10,611.50 | 58.59 |

INSPECTION

| | | |
|-----------------------------|--------------------------|--|
| Date of Assignment: | 29/11/2022 | JL Perfect Autowork Pte Ltd (HQ) |
| Date Inspected: | 29/11/2022 Inspected At: | 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit |
| Estimated Period of Repair: | 5.0 days | Singapore 415875 |

Adjuster: ADRIAN LING**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

| | | |
|---------------|--|--|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 27 Mar 2023) |
| Parts: | 143 | MERCEDES-BENZ CLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SNC8794H) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. Particulars | Condition | Repairer's | Amount |
|--|-----|---|----------------------|---|--------------------|
| 1 | 1 | *FRONT BUMPER | Deformed | 1,924.00 FL | *1,589.00 FL |
| 2 | 1 | *FRONT BUMPER LOGO | Necessary | 105.00 FL | *105.00 FL |
| 3 | 1 | *FRONT BUMPER SIDE GRILLE LH | Deformed | 126.00 FL | *126.00 FL |
| 4 | 2 | *FRONT BUMPER SENSOR LH | Damaged (1 PCS ONLY) | 470.00 FL | *235.00 FL |
| 5 | 6 | *FRONT BUMPER SENSOR HOLDER | Necessary | 270.00 FL | *150.00 FL |
| 6 | 2 | *FRONT BUMPER CENTER BRACKET | Not Necessary | 136.00 FL | *- FL |
| 7 | 1 | *FRONT BUMPER UPPER BEAM | Not Necessary | 192.00 FL | *- FL |
| 8 | 2 | *FRONT BUMPER UPPER BEAM SIDE SUPPORT | Not Necessary | 176.00 FL | *- FL |
| 9 | 1 | *FRONT BUMPER SIDE RETAINER LH | Damaged | 145.00 FL | *145.00 FL |
| 10 | 1 | *FRONT BUMPER LOWER GRILLE | Not Necessary | 385.00 FL | *- FL |
| 11 | 1 | *FRONT BUMPER REINFORCEMENT | Not Necessary | 568.00 FL | *- FL |
| 12 | 1 | *FRONT BUMPER SPONGE | Cracked | 193.00 FL | *193.00 FL |
| 13 | 1 | *FRONT BUMPER BOTTOM COVER GARNISH | Not Necessary | 388.00 FL | *- FL |
| 14 | 1 | *FRONT HEADLAMP (LED) | N/S Cracked | 7,084.00 FL | *3,542.00 FL |
| 15 | 1 | *FRONT HEADLAMP LOWER BRACKET SUPPORT LH | Not Necessary | 98.00 FL | *- FL |
| 16 | 1 | *FRONT GRILLE WITH CHROME | Cracked | 1,682.00 FL | *1,115.00 FL |
| 17 | 1 | *FRONT GRILLE SIDE AIR GUARD LH | Not Necessary | 141.00 FL | *- FL |
| 18 | 1 | *RADIATOR SUPPORT PANEL | Cracked | 820.00 FL | *820.00 FL |
| 19 | 1 | *RADIATOR AIR GUARD | Not Necessary | 86.00 FL | *- FL |
| 20 | 1 | *FRONT FENDER LH | Buckled | 886.00 FL | *886.00 FL |
| 21 | 1 | *FRONT FENDER COWLING (FRONT) LH | Deformed | 262.00 FL | *262.00 FL |
| 22 | 1 | *FRONT TURBO COOLER AIR GUARD | Not Necessary | 198.00 FL | *- FL |
| 23 | 1 | *SET FRONT BUMPER CLIP | Necessary | 120.00 FS | *30.00 FS |
| 24 | 1 | *SET FRONT BUMPER SIDE GRILLE CLIP | Necessary | 50.00 FS | *20.00 FS |
| 25 | 1 | *SET FRONT BUMPER BOTTOM COVER GARNISH CLIP | Not Necessary | 50.00 FS | *- FS |
| 26 | 1 | *SET FRONT NUMBER PLATE GARNISH CLIP | Not Necessary | 50.00 FS | *- FS |
| 27 | 1 | *SET FRONT FENDER COWLING CLIPS | Necessary | 80.00 FS | *30.00 FS |
| 28 | 1 | *SET SUPPORT PANEL UNDER COVER GARNISH CLIP | Not Necessary | 50.00 FS | *- FS |
| 29 | 1 | *RADIATOR COOLANT | Necessary | 180.00 FS | *50.00 FS |
| F=Franchise part. S=SpcNett. L=ListItemDisc. | | | | | |
| | | | | Sub Total (\$\$) | 16,915.00 9,298.00 |
| | | | | - List Item Discount on L Items 10.00/10.00% (\$\$) | 1,633.50 916.80 |
| | | | | Total Parts (\$\$) | 15,281.50 8,381.20 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|--|----------|------------|----------|
| Labour Items | | | | |
| 1 | PANEL BEATING ,REMOVING AND REPLACING PARTS | New | 1,200.00 | 500.00 |
| 2 | SPRAY PAINTING TO AFFECTED AREA | New | 1,000.00 | 400.00 |
| 3 | REFOCUS HEADLAMP BEAM | New | 80.00 | 0.00 |
| 4 | REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS | New | 120.00 | 60.00 |
| 5 | REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST | New | 80.00 | 60.00 |
| 6 | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC | New | 350.00 | 0.00 |
| Gross Labour Cost (S\$) | | | 2,830.00 | 1,020.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >