

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011954/TWP3Q2**Date:** 05/04/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00014362200

Claimant Vehicle No : SKR7744R **Insured Vehicle No :** SME654H

Date of Loss: 25/11/2022 Nature of Claim: TP Claim No: SNM22D208513/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKR7744R**

Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ3118290

Reg. Date: 29/07/2008 (Man. Year: 2008) Chassis No: JTDER12W003000310

Colour: Grey Odometer: 228268 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: LAUFENN 6 mm Rear Left Side: LAUFENN 6 mm

Front Right Side: LAUFENN 6 mm Rear Right Side: LAUFENN 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,183.12	3,260.10	5,923.02	64.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,020.00	1,720.00	2,300.00	57.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,203.12	4,980.10	8,223.02	62.28
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	13,203.12	4,000.00	9,203.12	69.70

INSPECTION

Date of Assignment: 29/11/2022

Date Inspected: 29/11/2022 Inspected At: Ky Auto Pte Ltd (HQ)
25 KAKI BUKIT ROAD 4 SYNERGY@KB #05-23
Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2023)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR7744R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	798.40 FL	*601.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	355.90 FL	*- FL
3	1		*FRONT BUMPER BRACKET N/S	Deformed	68.90 FL	*50.30 FL
4	1		*FRONT BUMPER SPONGE	Not Necessary	198.70 FL	*- FL
5	1		*FRONT BUMPER SIDE GARNISH N/S	Not Necessary	195.20 FL	*- FL
6	1		*FRONT BUMPER CLIPS	Necessary	41.25 FS	*30.00 FS
7	1		*HEADLAMP ASSY N/S	Cut	893.50 FL	*786.00 FL
8	1		*FRONT FENDER N/S	Bent	786.90 FL	*698.00 FL
9	1		*FRONT FENDER INNER SHIELD N/S	Deformed	296.80 FL	*158.00 FL
10	1		*FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	33.75 FS	*20.00 FS
11	1		*FRONT FENDER QUARTER GLASS MOULDING N/S	Not Necessary	298.70 FL	*- FL
12	1		*FRONT FENDER LAMP N/S	Not Necessary	98.60 FL	*- FL
13	1		*WING MIRROR ASSY W/LAMP N/S	Repair	495.80 FL	*- FL
14	1		*FRONT DOOR N/S	Repair	197.40 FL	*- FL
15	1		*FRONT DOOR UPPER HINGE N/S	Not Necessary	110.80 FL	*- FL
16	1		*FRONT DOOR LOWER HINGE N/S	Not Necessary	523.60 FL	*- FL
17	1		*FRONT DOOR INNER TRIMBOARD CLIPS	Not Necessary	198.70 FL	*- FL
18	1		*ROCKER GARNISH N/S	Not Necessary	145.30 FL	*- FL
19	1		*ROCKER GARNISH CLIPS	Not Necessary	235.70 FL	*- FL
20	1		*SHOCK ABSORBER N/S	Not Necessary	430.20 FL	*- FL
21	1		*FRONT LOWER ARM N/S	Not Necessary	495.80 FL	*- FL
22	1		*FRONT KNUCKLE ARM N/S	Bent	565.80 FL	*408.00 FL
23	1		*FRONT STEERING BALL JOINT N/S	Not Necessary	155.70 FL	*- FL
24	1		*FRONT KNUCKLE HUB BEARING N/S	Bent	435.20 FL	*245.50 FL
25	1		*FRONT DRI-SHAFT N/S	Not Necessary	1,015.90 FL	*- FL
26	1		*FRONT QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
27	1		*FRONT SPORT RIM N/S	Cut	750.00 FS	*650.00 FS
28	1		*FRONT TYRE N/S	Not Necessary	550.00 FS	*- FS
29	1		*FRONT BUMPER LOWER SPOILER	Cut	980.00 FS	*350.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (\$\$)						11,432.50 3,996.80
- List Item Discount on L Items 25.00/25.00% (\$\$)						2,249.38 736.70
Total Parts (\$\$)						9,183.12 3,260.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR,REMOVE & RENEW ON AFFECTED ACCIDENT AREAS	New	1,100.00	600.00
2	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,500.00	800.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	30.00
4	TO REMOVE & TRANSFER SPORT RIM & TYRE ,TO CONDUCT TYRE BALANCE	New	120.00	30.00
5	TO REMOVE & TRANSFER FRONT UNDERCARRIAGE COMPONENTS TO FACILITATE REPAIRS	New	250.00	150.00
6	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	New	150.00	80.00
7	TO REMOVE & INSTALL FRONT DOOR COMPONENTS TO FACILITATE REPAIRS	New	150.00	0.00
8	TO CONDUCT & RESET ECU DIAGNOSTIC PROGRAMME	New	450.00	0.00
9	TO RUST PROOF AFFECTED AREAS	New	250.00	30.00
Gross Labour Cost (\$\$)			4,020.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >