

ASS. REC BY: Toupin

REF: CS/CT122011954/TWP3

ASSIGNMENT

2023 July
2008 July

From: _____ Date: _____

Estimated Cost: _____

OD / TP / MS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 51KR 7744R Yr Regn: 2008 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Polya Wash C.C. 1794

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 228268 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STDER 12 W00300 SID.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: ---

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Laufenn

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 29/4/22

Survey held at Ky Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt n/s, f/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit \$5500

Date/Time, File Pass to?

☐ : Prel. Report

1) Date/Time, File Return to?

☐ : Final Report

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Report Format: _____

Lump Sum / L.B.J. () _____

KY AUTO PTE LTD

25 Kaki Bukit Road 4 #05-23 Synergy Building S417800

M (65) 9807 3304 Mr. Yap

F (65)

Email : kyautosg@gmail.com

Date: 28/11/2022

D.O.A 25/11/2022

SKR7744R Toyota Wish

→ SME654H

Damaged Area: Front Left Side

Parts / Material :

- | | |
|----|---|
| 1 | Front bumper |
| 2 | Front bumper reinforcement |
| 3 | Front bumper bracket n/s |
| 4 | Front bumper sponge |
| 5 | Front bumper side garnish n/s |
| 6 | Front bumper clips |
| 7 | Headlamp assy n/s |
| 8 | Front fender n/s |
| 9 | Front fender inner shield n/s |
| 10 | Front fender inner shield clips n/s |
| 11 | Front fender quarter glass moulding n/s |
| 12 | Front fender lamp n/s |
| 13 | Wing mirror assy w/lamp n/s |
| 14 | Front door n/s |
| 15 | Front door upper hinge n/s |
| 16 | Front door lower hinge n/s |
| 17 | Front door inner trimboard clips |
| 18 | Rocker garnish n/s |
| 19 | Rocker garnish clips |
| 20 | Shock absorber n/s |
| 21 | Front lower arm n/s |
| 22 | Front knuckle arm n/s |
| 23 | Front steering ball joint n/s |
| 24 | Front knuckle hub bearing n/s |
| 25 | Front dri-shaft n/s |

S	798.40	de
S	355.90	x
S	68.90	de
S	198.70	x
S	195.20	x
S	55.00	3000
S	893.50	ant
S	786.90	bt
S	296.80	?
S	45.00	?
S	298.70	✓
S	98.60	x
S	495.80	Ry
S	197.40	Ry
S	110.80	x
S	523.60	x
S	198.70	x
S	145.30	x
S	235.70	x
S	430.20	x
S	495.80	x
S	565.80	?
S	155.70	x
S	435.20	?
S	1,015.90	x

Parts : S 9,097.50

Less Parts 25% : S 2,274.37

Total Parts : \$ 6,823.12

Special Net Items :

Front quarter glass sealant

Front sport rim n/s

Front tyre n/s

Front bumper lower spoiler

S	80.00	x
S	750.00	ant-600
S	550.00	x
S	980.00	ant-300

Total S/N Parts : \$ 2,360.00

Labour :

To Repair, Remove & Renew On Affected Accident Areas @ SGD 350.00 per day	S	1,100.00	600
To Putty, Spray Paint on Affected Accident Areas @ SGD 300.00 per panel	S	1,500.00	800
To Check & Re-Connect all electrical wiring	S	50.00	30
To Remove & Transfer Sport Rim & Tyre, To Conduct Tyre Balance	S	120.00	30
To Remove & Transfer Front Undercarriage Components to Facilitate Repairs	S	250.00	150? plus
To Conduct Computerised Wheel Alignment	S	150.00	80
To Remove & Install Front Door Components To Facilitate Repairs	S	150.00	x
To Conduct & Reset ECU Diagnostic Programme	S	450.00	x
To Rust Proof Affected Areas	S	250.00	30
Total Labour :	\$	4,020.00	

TOTAL PARTS :	\$	6,823.12
TOTAL SPECIAL NET ITEM:	\$	2,360.00
TOTAL LABOUR :	\$	4,020.00
TOTAL REPAIR COST :	\$	13,203.12

Tan Hin 9249547
 'WP' 24/11/22 @ 230pm
 L/S 10 days after repair
 Tan Hin C (Kuantan)
 4 days
 To check repair unit.

MV \$8000
 Rebate: \$2439
 Net: \$5561
 Limit: \$5500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: