

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22011957/TNP3Q2**Date:** 04/01/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00025492202

**Claimant Vehicle No :** SFV911J **Insured Vehicle No :** YP6493R

Date of Loss: 26/11/2022 Nature of Claim: TP Claim No: SNM22D208534/C02/TOHHS

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SFV911J**

Make & Model: NISSAN X-TRAIL, 2.0 CVT (A) Engine No: MR20345575C

Reg. Date: 13/09/2018 (Man. Year: 2018) Chassis No: JN1JANT32Z0011414

Colour: White Odometer: 147877 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 225/55 R19 Rear Tyre Size: 225/55 R19

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,409.09	4,331.36	4,077.73	48.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	1,070.00	2,110.00	66.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,589.09</b>	<b>5,401.36</b>	<b>6,187.73</b>	<b>53.39</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,300.00</b>		
<b>(S\$)</b>	11,589.09	4,300.00	7,289.09	62.90
<b>+ GST 7.00/7.00% (S\$)</b>	811.24	301.00	510.24	62.90
<b>Nett Amount (S\$)</b>	<b>12,400.33</b>	<b>4,601.00</b>	<b>7,799.33</b>	<b>62.90</b>

**INSPECTION**

Date of Assignment: 29/11/2022

Date Inspected: 30/11/2022 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)  
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit  
Singapore 415875

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 04 Jan 2023)	
<b>Parts:</b>	N/A	NISSAN X-TRAIL 2.0 CVT (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFV911J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	594.10 FL	*594.10 FL
2	1		*FRONT BUMPER RH FOG LAMP	Not Necessary	258.90 FL	*- FL
3	1		*FRONT BUMPER RH FOG LAMP COVER	Not Necessary	87.80 FL	*- FL
4	1		*FRONT BUMPER RH SIDE RETAINER	Deformed	23.40 FL	*23.40 FL
5	1		*FRONT BUMPER LH SIDE RETAINER	Not Necessary	23.40 FL	*- FL
6	1		*RH HEADLAMP ASSY	Cracked	2,782.60 FL	*2,642.00 FL
7	1		*FRONT GRILLE EMBLEM	Not Necessary	74.00 FL	*- FL
8	1		*FRONT GRILLE	Not Necessary	411.40 FL	*- FL
9	1		*FRONT RH FENDER	Bent	641.70 FL	*641.70 FL
10	1		*FRONT RH FENDER SPLASH SHIELD	Not Necessary	132.60 FL	*- FL
11	1		*FRONT RH FENDER ARCH MOULDING	Cut	189.20 FL	*189.20 FL
12	1		*FRONT RH SPORT RIM	Cut	1,291.05 FS	*600.00 FS
13	1		*FRONT RH KNUCKLE ARM	Not Necessary	512.30 FL	*- FL
14	1		*FRONT RH WHEEL BEARING	Not Necessary	232.50 FL	*- FL
15	1		*FRONT RH SHOCK ABSORBER	Not Necessary	378.40 FL	*- FL
16	1		*FRONT RH SHOCK ABSORBER TOP MOUNTING	Not Necessary	83.70 FL	*- FL
17	1		*FRONT RH TIE ROD END	Not Necessary	127.60 FL	*- FL
18	1		*FRONT RH DOOR	Not Necessary	1,090.00 FL	*- FL
19	1		*FRONT RH DOOR FRAME BLACK TAPE STICKER	Not Necessary	32.00 FL	*- FL
20	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
21	1		*SET FRONT RH FENDER SPLASH SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
22	1		*SET FRONT RH FENDER ARCH MOULDING CLIPS	Necessary	70.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,176.65</b>	<b>4,740.40</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	767.56	409.04
<b>Total Parts (\$\$)</b>	<b>8,409.09</b>	<b>4,331.36</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS .TO PANEL BEATING ,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,200.00	400.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,000.00	500.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	60.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	60.00	30.00
5	REFOCUS AND ADJUST HEADLAMPS ASSY	New	80.00	30.00
6	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	180.00	80.00
7	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	450.00	0.00
8	REMOVE AND REPLACE FRONT RH DOOR INNER MECHANISM TO NEW DOOR	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,180.00</b>	<b>1,070.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >