

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011958/KVP3Q2**Date:** 17/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00048042202
Claimant Vehicle No :	SMK3000T	Insured Vehicle No :	SJW1897H
Date of Loss:	24/11/2022	Nature of Claim:	TP
		Claim No:	SNM22D208493/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK3000T	Engine No:	1AR1223575
Make & Model:	LEXUS RX270, 2.7 (A)	Chassis No:	JTJZA11A802477200
Reg. Date:	12/02/2015 (Man. Year: 2014)	Odometer:	0 km
Colour:	Metallic Grey		
Engine Capacity:	2672 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,428.00	9,311.55	5,116.45	35.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,560.00	2,370.00	2,190.00	48.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,988.00	11,681.55	7,306.45	38.48
Approved Total (Overridden) (S\$)		9,350.00		
(S\$)	18,988.00	9,350.00	9,638.00	50.76
+ GST 8.00/8.00% (S\$)	1,519.04	748.00	771.04	50.76
Nett Amount (S\$)	20,507.04	10,098.00	10,409.04	50.76

INSPECTION

Date of Assignment:	29/11/2022	
Date Inspected:	30/11/2022	Inspected At: Falcon-Air Auto Services Pte Ltd (Sin Ming) 176 Sin Ming Drive #01-06, Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	8.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Feb 2023)
Parts:	M1-SUV	LEXUS RX270 2.7 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK3000T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	867.13 FL	*867.13 FL
2	1		*LH REAR BUMPER SIDE RETAINER	Serviceable	131.87 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Repair	564.32 FL	*- FL
4	1		*REAR BUMPER SPONGE	Cracked	150.98 FL	*150.98 FL
5	1		*REAR END PANEL	Repair	878.02 FL	*- FL
6	1		*SPARE TYRE PANEL	Repair	938.83 FL	*- FL
7	1		*SPARE TYRE PANEL LOWER COVER	Buckled	490.00 FL	*490.00 FL
8	1		*EXHAUST PIPE (REAR)	Bent	1,351.69 FL	*1,351.69 FL
9	1		*BONNET	Bent	1,670.48 FL	*1,670.48 FL
10	1		*RADIATOR SUPPORT PANEL	Repair	1,907.00 FL	*- FL
11	1		*FRONT BRACE PANEL	Repair	110.00 FL	*- FL
12	1		*FRONT GRILLE	Dented	1,113.42 FL	*1,113.42 FL
13	1		*FRONT GRILLE LOGO	Scratched	501.44 FL	*501.44 FL
14	1		*FRONT BUMPER	Buckled	965.67 FL	*965.67 FL
15	1		*FRONT BUMPER CENTRE GARNISH	Distorted	133.41 FL	*133.41 FL
16	1		*FRONT BUMPER LOWER GRILLE	Distorted	235.00 FL	*235.00 FL
17	1		*FRONT BUMPER REINFORCEMENT	Repair	679.28 FL	*- FL
18	1		*FRONT BUMPER SPONGE	Cracked	127.10 FL	*127.10 FL
19	1		*TOW COVER	O/S Dented	320.00 FL	*160.00 FL
20	2		*REAR BUMPER LAMP	N/S Mtg Cracked / O/S Cracked	1,611.94 FL	*1,611.94 FL
21	2		*EXHAUST RUBBER HOLDER	Missing	73.48 FL	*73.48 FL
22	1		*EXHAUST GASKET	Necessary	60.00 FL	*60.00 FL
23	1		*FRONT NUMBER PLATE BASE	Dented	144.85 FL	*144.85 FL
24	1		*RH FRONT PARKING SENSOR	Serviceable	315.62 FL	*- FL
25	1		*REVERSE SENSOR	Scratched	315.62 FS	*315.62 FS
26	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*60.00 FS
27	1		*SET BONNET INSULATOR CLIP	Necessary	40.00 FS	*40.00 FS
28	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*45.00 FS
29	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*80.00 FS
30	1		*SET RADIATOR SUPPORT TOP GARNISH CLIP	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,962.15	10,277.21
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,534.15	965.66
Total Parts (\$\$)	14,428.00	9,311.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE /REFIX EXHAUST PIPE	New	150.00	80.00
2	TO RUSTPROOF ACCIDENT DAMAGE AREA	New	150.00	0.00
3	TO APPLY BODY SEALANT TO CAR JOINTS	New	100.00	0.00
4	TO VACUUM RE-OIL AND RE-GAS AIR CON	New	120.00	0.00
5	TO CHECK REAR WIRING	New	80.00	40.00
6	TO REFIX REVERSE & FRONT PARKING SENSOR	New	100.00	100.00
7	TO REMOVE TRIMS ,SEAT ,GARNISH	New	280.00	0.00
8	TO REMOVE /REFIX SPARE TYRE UNDERCOVER	New	80.00	0.00
9	TO CUT OUT /REWELD REAR END PANEL ,SPARE TYRE PANEL REPAIR REAR CHASSIS INCLUDING REPLACEMENT OF PARTS	New	900.00	600.00
10	TO CUT OUT /REWELD RADIATOR SUPPORT PANEL,REPAIR FRONT CHASSIS INCLUDING REPLACEMENT OF PARTS (FRONT PORTION)	New	800.00	450.00
11	TO SPRAY PAINT ON BONNET ,RADIATOR SUPPORT PANEL ,FRONT BUMPER ,REAR BUMPER,REAR END PANEL,SPARE TYRE PANEL	New	1,800.00	1,100.00
Gross Labour Cost (S\$)			4,560.00	2,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >