

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22001918/Vqy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 29/03/2022 SINGAPORE 068811 ATTN: TEO KITTY Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SMM 1048J FBR 7685J Veh. Inspected Policy No. P2302946 Coverage (\$) 0.00 Claim No. S2M03TNQ Excess (\$) 0.00 01/03/2022 **TEO KITTY Assign Date** Assign From **Vehicle Particulars & Condition** 2. YAMAHA AEROX 155 Make & Model C.C HIDDEN 2020 Engine No. Year of Reg. MH3SG4640LJ072913 **BLACK** Chassis No. Colour Odometer Steering **JAMMED IN ORDER** STANDARD ALLOY RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 140/70-14 TIMSUN 6 mm L/H Front Tyre mm 140/70-14 TIMSUN R/H Rear Tyre 6 mm L/H Rear Tyre mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S 5. **General Information** 17/02/2022 Inspect Date / Time 01/03/2022 (11:29 AM) Accident Date **EQUATOR BROTHERHOOD** Survey held at 25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/ASM22001918/Vqy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

ESTIMATED NORMAL PERIOD FOR REPAIR:

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

4 Working Days