

Vehicle Damage Assessment Report for [SHB4487Y]

Estimate Created: 28/12/2022 00:41 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 29/12/2022 02:53 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Hyundai	Model	i40
Engine Type			
License Plate Number	SHB4487Y	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$1,250.00 WITH 2 DAYS

Insurlogic 5 (29/12/2022 02:51)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
WHEEL HUB CAP RR LH		1	214.20	-20.00 %	171.36
Parts Subtotal					171.36

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR DOOR COMFORTDELGRO & APPS STICKER LH		1.0	80.00	0.00 %	80.00
RENEW ADVERTISEMENT STICKER		1.0	200.00	0.00 %	200.00
Materials Subtotal					280.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
PANEL BEATING	RnR	525.00	0.00 %	525.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
REAR DOOR LH	Medium	0.00	0.00 %	0.00
REAR FENDER LH	Medium	0.00	0.00 %	0.00
ROCKER COVER GARNISH LH	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINTING CHARGE	Full spray	600.00	0.00 %	600.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 525.00

Paint Labor Subtotal 600.00

Labor Subtotal 1,125.00

Summary

Repair Cost 1,576.36

Discount(20 %) (315.27)

1,261.09

Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	1,261.09