

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22011981/AVCM4**Date:** 06/07/2023**REFERENCE**

Insured/Claimant:	LIM BAK CHIM	Policy No:	1800022296-04	
Date of Loss:	01/10/2022	Nature of Claim:	OD	Claim No: 5704845339SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW8190S		
Make & Model:	AUDI A3, 999cc SEDAN 1.0 TFSI S TRONIC (LED) (A)	Engine No:	CHZ653023
Reg. Date:	08/03/2018 (Man. Year: 2017)	Chassis No:	WAUZZZ8V6J1046233
Colour:	White	Odometer:	89424 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,199.00	5,765.52	10,433.48	64.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,052.00	4,102.00	6,950.00	62.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	27,251.00	9,867.52	17,383.48	63.79
+ GST 8.00/8.00% (S\$)	2,180.08	789.40	1,390.68	63.79
Nett Amount (S\$)	29,431.08	10,656.92	18,774.16	63.79

INSPECTION

Date of Assignment:	30/11/2022		
Date Inspected:	29/11/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,317.00 FS	*1,853.60 FS
2	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	36.00 FS	*- FS
3	1		*REAR BUMPER LOCKING MECHANISM	Not Necessary	34.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Deformed	264.00 FS	*210.80 FS
5	1		*REAR BUMPER REFLECTOR - RH	Not Necessary	46.00 FS	*- FS
6	1		*REAR OUTER TAIL LIGHT - RH	Not Necessary	974.00 FS	*- FS
7	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	74.00 FS	*- FS
8	1		*REAR DOOR	Repair	3,265.00 FS	*- FS
9	1		*REAR OUTER DOOR SEAL - RH	Not Necessary	179.00 FS	*- FS
10	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
11	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
12	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
13	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	134.00 FS	*- FS
14	1		*REAR DOOR CATCH - RH	Not Necessary	105.00 FS	*- FS
15	1		*FRONT DOOR	Dented	3,265.00 FS	*2,612.00 FS
16	1		*FRONT OUTER DOOR SEAL - RH	Necessary	179.00 FS	*142.80 FS
17	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
18	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
19	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
20	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	252.00 FS	*- FS
21	1		*FRONT DOOR CATCH - RH	Not Necessary	116.00 FS	*- FS
22	1		*FRONT DOOR HANDLE - RH	Not Necessary	398.00 FS	*- FS
23	1		*FRONT DOOR HANDLE END CAP - RH	Not Necessary	62.00 FS	*- FS
24	1		*FRONT WING MIRROR MOUNTING - RH	Cut	1,130.00 FS	*904.00 FS
25	1		*FRONT WING MIRROR CAP - RH	Repair	180.00 FS	*- FS
26	1		*FRONT WING MIRROR GLASS - RH	Not Necessary	1,776.00 FS	*- FS
27	1		*FRONT WINDOW REGULATOR - RH	Not Necessary	286.00 FS	*- FS
28	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	183.00 FS	*- FS
29	1		*REAR PARKING AID SENSOR - INNER / OUTER	Not Necessary	266.00 FS	*- FS
30	4		*REAR PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
31	1		*RHS FRONT RIM (TBC) (NPA)	Not Necessary	0.00 FS	*- FS
32	1		*SUNDRIES	Necessary	400.00 FS	*42.32 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **16,199.00** **5,765.52**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	280.00
2	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	800.00	280.00
3	TO DISMANTLE AND RENEW REAR BUMPER, RHS REAR DOOR AND RHS FRONT DOOR. TO REPAIR RHS REAR FENDER AND RHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,000.00	1,000.00
4	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, RHS FRONT DOOR, DOOR HANDLE, RHS WING MIRROR COVER AND RHS FRONT FENDER	New	5,500.00	2,350.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			11,052.00	4,102.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >