

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22011984/RVCE2**Date:** 29/03/2023**REFERENCE**

Insured/Claimant:	Julie Chew Li Chin	Policy No:	2100397324	
Date of Loss:	27/11/2022	Nature of Claim:	OD	Claim No: 8473155387SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ7540S	Engine No:	CHP184642
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZ8U3ER134364
Reg. Date:	24/12/2014 (Man. Year: 2014)	Odometer:	64210 km
Colour:	Orange		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$53,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R17	Rear Tyre Size:	235/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,851.00	6,501.12	17,349.88	72.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,764.00	6,754.00	3,010.00	30.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	33,615.00	13,255.12	20,359.88	60.57
- Excess (\$\$)	800.00	800.00	0.00	0.00
(\$\$)	32,815.00	12,455.12	20,359.88	62.04
+ GST 8.00/8.00% (\$\$)	2,625.20	996.41	1,628.79	62.04
Nett Amount (\$\$)	35,440.20	13,451.53	21,988.67	62.04

INSPECTION

Date of Assignment:	30/11/2022	
Date Inspected:	29/11/2022	Inspected At: 24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Scratched	1,205.00 FS	*963.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	114.00 FS	*- FS
3	1		*FRONT BUMPER SPOILER	Scratched	426.00 FS	*340.80 FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER AIR GRILLE - RH	Scratched	132.00 FS	*105.60 FS
6	1		*FRONT BUMPER AIR GRILLE TRIM - RH	Not Necessary	27.00 FS	*- FS
7	1		*FRONT BUMPER FORM FILLER PIECE	Not Necessary	114.00 FS	*- FS
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	974.00 FS	*- FS
9	1		*FRONT BUMPER REINFORCEMENT COVER	Not Necessary	73.00 FS	*- FS
10	1		*FRONT BUMPER STRIKER PLATE	Not Necessary	146.00 FS	*- FS
11	1		*FRONT BUMPER TOP COVER	Not Necessary	137.00 FS	*- FS
12	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
13	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	56.00 FS	*- FS
14	2		*FRONT FENDER BRACE RH - UPPER / LOWER	Not Necessary	134.00 FS	*- FS
15	1		*FRONT FENDER - RH	Bent	1,014.00 FS	*811.20 FS
16	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	73.00 FS	*- FS
17	1		*FRONT FENDER BRACKET	Not Necessary	92.00 FS	*- FS
18	1		*FRONT FENDER RIVET (12pcs)	Necessary	36.00 FS	*28.48 FS
19	1		*FRONT FENDER BRACE RH - FRONT	Bent	116.00 FS	*92.80 FS
20	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	37.00 FS	*- FS
21	1		*FRONT WHEEL HOUSING LINER - RH	Scratched	260.00 FS	*208.00 FS
22	1		*FRONT WHEEL SPOILER - RH	Cracked	152.00 FS	*136.00 FS
23	1		*HEADLIGHT MOUNTING - RH	Cracked	132.00 FS	*105.20 FS
24	1		*HEADLIGHT RETAINING PLATE - RH	Cracked	97.00 FS	*77.04 FS
25	1		*HEADLIGHT - RH	Not Necessary	2,182.00 FS	*- FS
26	1		*HEADLIGHT LIFT CYLINDER - RH	Not Necessary	231.00 FS	*- FS
27	1		*HEADLIGHT LIFT CYLINDER HOSE	Not Necessary	204.00 FS	*- FS
28	1		*FRONT FOG LAMP - RH	Not Necessary	304.00 FS	*- FS
29	2		*FRONT WHEEL ARCH TRIM - LH / RH	Necessary	544.00 FS	*435.20 FS
30	18		*GROMMET	Not Necessary	53.00 FS	*- FS
31	1		*FRONT RIM - RH	Scratched	1,414.00 FS	*1,131.20 FS
32	1		*RUBBER VALVE	Necessary	4.00 FS	*2.96 FS
33	1		*FRONT ASSEMBLY CARRIER	Not Necessary	1,567.00 FS	*- FS
34	1		*FRONT WISHBONE - RH	Bent	520.00 FS	*416.00 FS
35	1		*FRONT WHEEL BEARING HOUSING - RH	Bent	628.00 FS	*502.40 FS
36	1		*FRONT GUIDE JOINT - RH	Bent	139.00 FS	*110.80 FS
37	1		*FRONT STABILIZER	Not Necessary	467.00 FS	*- FS
38	1		*FRONT COUPLING ROD	Not Necessary	105.00 FS	*- FS
39	1		*FRONT WHEEL BEARING - RH	Necessary	486.00 FS	*388.80 FS
40	1		*FRONT ABSORBER - RH	Bent	364.00 FS	*290.80 FS
41	1		*FRONT DRIVER SHAFT	Not Necessary	1,521.00 FS	*- FS
42	1		*FRONT STEERING RACK	Not Necessary	5,552.00 FS	*- FS
43	1		*FRONT TRACK ROD - RH	Bent	99.00 FS	*78.56 FS
44	1		*FRONT TIE ROD END - RH	Bent	126.00 FS	*100.40 FS
45	1		*FRONT TYRE - RH (NPA)	Not Necessary	0.00 FS	*- FS
46	1		*SUNDRIES	Not Necessary	1,000.00 FS	*- FS
47	1		*SUNDRIES	Necessary	300.00 FS	*75.28 FS
48	1		*WATER DEFLECTOR STRIP-RH (Supplementary)	Cracked	75.00 FS	*60.00 FS
49	1		*SUSPENSION STRUT STORAGE-RH (Supplementary)	Not Necessary	106.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*DEEP GROOVE BALL THRUST BEARING-RH (Supplementary)	Not Necessary	51.00 FS	*- FS
51	1		*REPAIR SET FOR STEERING BOX (Supplementary)	Necessary	50.00 FS	*40.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					23,851.00	6,501.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,500.00	1,650.00
5	TO RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	3,200.00	3,200.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
7	TO RENEW RHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
Gross Labour Cost (\$\$)			9,764.00	6,754.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >