

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III22009623/SNY3E2-1**Date:** 14/12/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MFL0003414_03
Claimant Vehicle No : SLQ3022K **Insured Vehicle No :** SNG7454A
 Date of Loss: 27/09/2022 Nature of Claim: TP Claim No: MFL2022D0005447

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ3022K**
 Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4409753
 Reg. Date: 03/07/2017 (Man. Year: 2016) Chassis No: RU11209753
 Colour: Red Odometer: 36181 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 7 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,985.94	4,746.11	8,239.83	63.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,700.00	1,240.00	3,460.00	73.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,685.94	5,986.11	11,699.83	66.15
Approved Total (Overridden) (S\$)		4,750.00		
(S\$)	17,685.94	4,750.00	12,935.94	73.14
+ GST 7.00/7.00% (S\$)	1,238.02	332.50	905.52	73.14
Nett Amount (S\$)	18,923.96	5,082.50	13,841.46	73.14

INSPECTION

Date of Assignment: 30/11/2022
 Date Inspected: 29/09/2022 Inspected At: Providence Automobile Pte Ltd (HQ)
 11 KAKI BUKIT ROAD 1 #03-08 EUNOS
 TECHNOLINK
 Singapore 415939
 Estimated Period of Repair: 5.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Dec 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ3022K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Repair	1,289.00 FL	*- FL
2	1		*FRONT RH DOOR WEATHERSTRIP	Not Necessary	283.60 FL	*- FL
3	1		*FRONT RH FENDER	Buckled	858.70 FL	*858.70 FL
4	1		*FRONT RH FENDER INNER SHIELD	Not Necessary	235.90 FL	*- FL
5	1		*SET FRONT RH FENDER INNER SHIELD CLIPS	Necessary	53.50 FL	*35.00 FL
6	1		*FRONT RH FENDER ARCH PROTECTOR	Cracked	283.60 FL	*283.60 FL
7	1		*SET FRONT RH FENDER ARCH PROTECTOR CLIPS	Necessary	53.50 FL	*30.00 FL
8	1		*FRONT RH HEADLAMP	Cracked	2,145.90 FL	*2,145.90 FL
9	1		*FRONT RH HEADLAMP LOWER BRACKET	Cracked	235.40 FL	*235.40 FL
10	1		*FRONT BUMPER	Deformed / Cracked	1,050.10 FL	*1,050.10 FL
11	1		*FRONT BUMPER SIDE RETAINER (N/S NOT NECESSARY)	O/S Deformed/Cracked/	256.28 FL	*128.14 FL
12	1		*SET FRONT BUMPER CLIPS	Cracked	53.50 FL	*35.00 FL
13	1		*FRONT BUMPER FOG LAMP	Not Necessary	456.70 FL	*- FL
14	1		*FRONT BUMPER FOG LAMP GARNISH	Cut	176.60 FL	*176.60 FL
15	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	588.25 FL	*- FL
16	1		*FRONT BUMPER LOWER SPOILER	Grazed / Deformed	485.60 FL	*485.60 FL
17	1		*FRONT BUMPER LOWER SPOILER RUBBER	Not Necessary	202.10 FL	*- FL
18	1		*SET FRONT BUMPER LOWER SPOILER RUBBER CLIPS	Not Necessary	53.50 FL	*- FL
19	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	180.10 FL	*- FL
20	1		*FRONT RH SHOCK ABSORBER	Not Necessary	571.30 FL	*- FL
21	1		*FRONT RH LOWER ARM	Not Necessary	488.90 FL	*- FL
22	1		*FRONT RH KNUCKLE ARM	Not Necessary	561.60 FL	*- FL
23	1		*FRONT RH KNUCKLE ARM BEARING	Not Necessary	197.60 FL	*- FL
24	1		*FRONT STABILIZER BAR	Not Necessary	195.80 FL	*- FL
25	1		*FRONT STABILIZER BAR RH LINK	Not Necessary	195.80 FL	*- FL
26	1		*FRONT RH DRIVE SHAFT	Not Necessary	588.50 FL	*- FL
27	1		*FRONT GRILLE	Not Necessary	582.30 FL	*- FL
28	1		*FRONT GRILLE LOGO (H)	Not Necessary	89.10 FL	*- FL
29	1		*FRONT GRILLE BASE	Cracked	413.60 FL	*413.60 FL
30	1		*FRONT GRILLE CHROME	Not Necessary	368.10 FL	*- FL
31	1		*FRONT GRILLE TOP BRACKET	Not Necessary	198.10 FL	*- FL
32	1		*SET FRONT GRILLE CLIPS	Cracked	53.50 FL	*30.00 FL
33	1		*WIPER TANK	Not Necessary	265.80 FL	*- FL
34	1		*WIPER TANK MOTOR	Not Necessary	150.80 FL	*- FL
35	1		*FRONT RH WIND MIRROR (GRAZED)	Not Consistent With the Impact	994.50 FL	*- FL
36	1		*FRONT RH WIND MIRROR COVER (REPAIR)	Not Consistent With The Impact	125.30 FL	*- FL
37	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
38	1		*FRONT NUMBER PLATE HOLDER	Cracked	50.00 FS	*20.00 FS
39	1		*FRONT RH RIM	Repair	600.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT RH TYRE	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	15,982.43 5,927.64
					- List Item Discount on L Items 20.00/20.00% (\$\$)	2,996.49 1,181.53
					Total Parts (\$\$)	12,985.94 4,746.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS, ALL RELEVANT ATTACHMENT, FITTING TO COMMENCE REPAIRS, REPLACE THE DAMAGES PARTS, REINSTALL & REALIGN ALL NECESSARY PARTS	New	1,600.00	500.00
2	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS	New	50.00	30.00
3	TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED PANEL FOR RUST PROTECTION	New	50.00	30.00
4	DIAGNOSTIC & RESET FAULT CODE	New	400.00	0.00
5	TO CONDUCT RIM BALANCING	New	100.00	20.00
6	TO REMOVE, RENEW AND REFIT THE FRONT UNDERCARRIAGE TO FACILITATE REPAIR	New	300.00	0.00
7	TO REMOVE, RENEW AND REFIT TYRE	New	50.00	0.00
8	TO REMOVE, RENEW AND REFIT RACK & PINION ASSY TO FACILITATE REPAIR	New	400.00	0.00
9	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY ALL ACCIDENT DAMAGE PARTS AND OTHER AFFECTED AREA / PANEL	New	1,600.00	600.00
10	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
Gross Labour Cost (S\$)			4,700.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >