

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22011989/KYA3Q2**Date:** 11/05/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01
Claimant Vehicle No : SLG6222H **Insured Vehicle No :** SLN4960L
 Date of Loss: 28/11/2022 Nature of Claim: TP Claim No: MFL2022D0010724

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG6222H**
 Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT ABS (A) Engine No: 2ZRR822446
 Reg. Date: 06/10/2016 (Man. Year: 2016) Chassis No: ZVW506010136
 Colour: Metallic Grey Odometer: 437205 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Arivo 9 mm Rear Left Side: Arivo 9 mm
 Front Right Side: Arivo 9 mm Rear Right Side: Arivo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,759.80	3,025.66	4,734.14	61.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,470.00	870.00	37.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,099.80	4,495.66	5,604.14	55.49
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	10,099.80	3,600.00	6,499.80	64.36
+ GST 7.00/7.00% (S\$)	706.99	252.00	454.99	64.36
Nett Amount (S\$)	10,806.79	3,852.00	6,954.79	64.36
+ Loss of Use (5.0 x S\$70.00/day) (S\$)		350.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,209.45		

INSPECTION

Date of Assignment: 30/11/2022
 Date Inspected: 30/11/2022 Inspected At: Hui Yang Motor Pte Ltd (HQ)
 176 Sin Ming Drive #04-02, Sin Ming AutoCare
 Singapore 575721
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jan 2023)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT ABS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG6222H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	978.25 FL	*978.25 FL
2	1		*REAR TAILGATE PRIUS EMBLEM	Necessary	61.75 FL	*61.75 FL
3	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	53.75 FL	*53.75 FL
4	1		*REAR TAILGATE TOYOTA LOGO	Necessary	61.10 FL	*61.10 FL
5	1		*REAR TAILGATE OUTER GARNISH	Mtg Cracked	741.35 FL	*741.35 FL
6	1		*REAR TAILGATE INNER RUBBER	Serviceable	281.50 FL	*- FL
7	1		*REAR TAILGATE INNER GARNISH	Serviceable	381.00 FL	*- FL
8	2		*REAR TAILLAMP	Serviceable	1,123.20 FL	*- FL
9	2		*REAR TAILLAMP INNER COVER	Serviceable	243.00 FL	*- FL
10	1		*REAR BUMPER	Buckled	928.35 FL	*497.50 FL
11	1		*REAR BUMPER SIDE RETAINER	O/S Distorted	282.80 FL	*141.40 FL
12	2		*REAR BUMPER SIDE LAMP	Serviceable	742.90 FL	*- FL
13	1		*REAR BUMPER SIDE LOWER GARNISH	O/S Mtg Cracked	548.90 FL	*274.45 FL
14	2		*REAR BUMPER SIDE INNER GARNISH	Serviceable	563.80 FL	*- FL
15	1		*REAR BUMPER DIFFUSER	Bent	379.00 FL	*379.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	458.00 FL	*458.00 FL
17	1		*REAR BUMPER TOWING COVER	Dented	61.00 FL	*61.00 FL
18	1		*REAR BUMPER LOWER CENTRE COVER	Serviceable	281.50 FL	*- FL
19	2		*REAR BUMPER LOWER SIDE COVER	Serviceable	383.10 FL	*- FL
20	1		*REAR END PANEL	Repair	970.25 FL	*- FL
21	1		*REAR END PANEL INNER GARNISH	Serviceable	381.90 FL	*- FL
22	1		*SET REAR NUMBER PLATE & CASING	Dented	50.00 FS	*45.00 FS
23	1		*SET REAR PARKING SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,236.40	3,952.55
- List Item Discount on L Items 25.00/25.00% (S\$)	2,476.60	926.89
Total Parts (S\$)	7,759.80	3,025.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
2	TUFFKOTE	New	120.00	30.00
3	WIRING	New	100.00	20.00
4	SPRAY PAINTING	New	1,000.00	800.00
5	LABOUR CHARGES	New	1,000.00	500.00
Gross Labour Cost (S\$)			2,340.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >