

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22011994/UPA3Q2**Date:** 04/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000071
Claimant Vehicle No :	SLE8367X	Insured Vehicle No :	GBL5879L
Date of Loss:	28/11/2022	Nature of Claim:	TP
		Claim No:	9908929661SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE8367X		
Make & Model:	MERCEDES-BENZ GLC 250, 2.0 4MATIC (A)	Engine No:	27492030545474
Reg. Date:	02/08/2016 (Man. Year: 2016)	Chassis No:	WDC2539462F053180
Colour:	Grey	Odometer:	85049 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,944.95	10,345.09	8,599.86	45.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	1,230.00	1,140.00	48.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,314.95	11,575.09	9,739.86	45.69
Approved Total (Overridden) (S\$)		9,200.00		
Nett Amount (S\$)	21,314.95	9,200.00	12,114.95	56.84
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	30/11/2022	
Date Inspected:	30/11/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut / Deformed	2,115.32 F	*1,623.02 FL
2	1		*FRONT BUMPER BEAM	Not Necessary	845.10 F	*- FL
3	1		*FRONT BUMPER SIDE RETAINER N/S	Bent	105.00 F	*102.50 FL
4	2		*FRONT BUMPER PDC SENSORS	Serviceable	380.00 F	*- FL
5	1		*SET FRONT BUMPER CLIPS & RIVET	Necessary	60.00 F	*60.00 FL
6	1		*FRONT BUMPER LOWER	Grazed	761.00 F	*360.07 FL
7	1		*FRONT BUMPER LOGO	Not Necessary	85.00 F	*- FL
8	1		*FRONT BUMPER SPONGE	Torn	162.00 F	*160.50 FL
9	1		*FRONT HEADLAMP N/S	Cracked	6,500.00 F	*3,208.95 FL
10	1		*FRONT SUPPORT PANEL	Not Necessary	845.11 F	*- FL
11	1		*FRONT FENDER N/S	Dented	1,218.00 F	*942.01 FL
12	1		*FRONT FENDER INNER SHIELD N/S	Twisted	381.00 F	*288.50 FL
13	1		*SET FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	60.00 F	*60.00 FL
14	1		*FRONT FENDER OUTER PROTECTOR N/S	Grazed	485.12 F	*366.00 FL
15	1		*FRONT SPORT RIM 18 INCH	Warped	1,500.00 F	*1,200.00 FL
16	1		*FRONT LOWER ARM N/S	Twisted	611.20 F	*525.00 FL
17	1		*FRONT KNUCKLE ARM N/S	Bent	1,006.00 F	*1,006.00 FL
18	1		*FRONT WHEEL HUB BEARING N/S	Damaged	650.00 F	*450.00 FL
19	1		*FRONT TOP ARM N/S	Twisted	355.10 F	*322.00 FL
20	1		*FRONT SHOCK ABSORBER N/S	Bent	820.00 F	*820.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	18,944.95	11,494.55
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,149.46
Total Parts (\$\$)	18,944.95	10,345.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED FRT PDC SENSOR	New	80.00	50.00
3	TO SPRAY RUST PROOFING	New	80.00	30.00
4	TO CONDUCT WHEEL ALIGNMENT	New	120.00	100.00
5	TO DISMANTLE & REPLACED FRT UNDER CARRIAGE	New	280.00	150.00
6	TO RESET & REPROGRAMMING SYSTEM	New	180.00	80.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	780.00	400.00
8	TO PUTTY & SPRAY PAINTING	New	800.00	400.00
Gross Labour Cost (S\$)			2,370.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >