



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lim Teck Hock	Cust No/Name /Yap Hwee Hwang
Blk 928 Hougang Street 91	Reg No/Reg Date SLP5363T / 09/06/2014
#09-53	Date In/Mileage 29/11/2022/ 105004
Singapore 530928	Chassis No JMYSRCY1AGU006872
Contact No Mobile: 96529703	Engine No 4A92CP5273
	Make/Model MIT/16MY LANCER EX 1.6 4AT (E21)
	Colour/Trim U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	29/11/2022/ 13:53	LER	972 / Mars Ler	13011
Description of Goods / Services					
		Qty	Unit Price	Disc%	Amount
Z TEXT					
ACCIDENT ON 29/11/2022 ALONG NEAR BLK 534 PASIR RIS DR 1 OPEN CARPARK					
OWNER CLAIMING THIRD PARTY					
REQUIRED REPLACEMENT CAR					
TP # YP170L TP INS : CHINA TAIPING					
M SUNDRY					
TO APPLY SELANT KIT ON NEW PANEL					80 ✓ 160.00
M SUNDRY					
TO APPLY ANTI-CORROSION ON ACCIDENT AFFECTED AREAS					100 ✓ 200.00
B WHEELALIGNMENT120L					
To Conduct Computerize Full Wheel Alignment					✓ 180.00 ✓
E PNT88000					
WHEEL BALANCING					✓ 50.00 ✓
E PNT88000					
TYRE YOKOHAMA AE51 x 1Pc					80 ✓ 280.00
E PNT88000					
TO REPLACE FRT BUMPER,RHF FENDER,ETC					1920 ✓ 2560.00 ✓
-TO REPAIR RHF SUPPORT PNL,RHF FENDER APRON,RHF DOOR PANEL,HOOD					
STRAIGHTEN,REFORM,ALIGN ON RHS ACCIDENT AFFECTED AREAS					
E PNT98000					
SPRAY PAINTING ON RHS ACCIDENT AFFECTED AREAS					2200 ✓ 3300.00
A 10028901					
TO CONDUCT DIAGNOSTIC CHECK ON USING MUT TESTER AND CLEAR TROUBLE COD					✓ 280.00 ✓
A 54900099					
CHECK WIRING & ELECTRICAL SYSTEM					80 ✓ 100.00
M FACE,FR BUMPER		1.00	739.00	00.00	4 ✓ 739.00 ✓
M RIVET,FR BUMPER		12.00	4.00	00.00	4 ✓ 48.00 ✓
M CLIP,FR BUMPER		10.00	4.00	00.00	4 ✓ 40.00 ✓
M COVER,HEADLAMP SUPT PANEL		1.00	61.00	00.00	80 ✓ 61.00 ✓
M BRACKET,FR BUMPER SIDE,LH		1.00	15.00	00.00	80 ✓ 15.00 ✓
M BRACKET,FR BUMPER SIDE,RH		1.00	15.00	00.00	80 ✓ 15.00 ✓
M GARNISH,FR BUMPER,RH		1.00	37.00	00.00	80 ✓ 37.00 ✓
M LAMP ASSY,SIDE MARKER,RH		1.00	616.00	00.00	80 ✓ 616.00 ✓

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

MITSUBISHI
MOTORS

ESTIMATE

Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lim Teck Hock Blk 928 Hougang Street 91 #09-53 Singapore 530928 Contact No Mobile: 96529703	Cust No/Name /Yap Hwee Hwang Reg No/Reg Date SLP5363T / 09/06/2017 Date In/Mileage 29/11/2022/ 105004 Chassis No JMYSRCY1AGU006872 Engine No 4A92CP5273 Make/Model MIT/16MY LANCER EX 1.6 4AT (E21) Colour/Trim U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	29/11/2022/ 13:53	LER	972 / Mars Ler	13011
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M LAMP ASSY, FOG, FR LH		1.00	308.00	00.00	Run 308.00
M GRILLE, RADIATOR		1.00	272.00	00.00	Run 272.00
M MARK, THREE-DIA		1.00	39.00	00.00	Run 39.00
M HEADLAMP ASSY, RH		1.00	682.00	00.00	Run 682.00
M TANK, WINDSHIELD WASHER		1.00	91.00	00.00	Run 91.00
M MOTOR, WINDSHIELD WASHER(*)		1.00	156.00	00.00	Run 156.00
M GASKET, W/SHLD WASHER TANK		1.00	4.00	00.00	Run 4.00
M SHIELD, FR FENDER, FR RH		1.00	120.00	00.00	Run 120.00
M CLIP, SPLASH SHIELD		10.00	4.00	00.00	Run 40.00
M FENDER, FR RH		1.00	528.00	00.00	Run 528.00
M BRACKET, FR FENDER, RH		1.00	14.00	00.00	Run 14.00
M GARNISH, FR FENDER RH		1.00	57.00	00.00	Run 57.00
M WHEEL, DISC		1.00	1450.00	00.00	Run 1450.00

Estimate

4043

4043
489098933
#6 days

SURVEYOR NAME:

Tanfahm 97495749 / 62563561

SURVEYOR SIGNATURE:

Tanfahm

DATE:

01/12/22 @ 10:50am

REMARKS:

Remun before paint.

Tanfahm @ khauto.com

06 days

WP

Confirm & accepted by

Authorized signatory and company stamp

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

7% GST on

Nett	12,442.00
	870.94
Total Payable	13,312.94

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. Signatory should mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.