

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22011999/TWP3Q2**Date:** 17/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00042932203
<b>Claimant Vehicle No :</b>	SLP5363T	<b>Insured Vehicle No :</b>	YP170L
Date of Loss:	29/11/2022	Nature of Claim:	TP
		Claim No:	SNM22D208577/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLP5363T</b>	Engine No:	4A92CP5273
Make & Model:	MITSUBISHI LANCER, 1.6 EX SPORTS (M)	Chassis No:	JMYSRCY1AGU006872
Reg. Date:	09/06/2017 (Man. Year: 2017)	Odometer:	105007 km
Colour:	Silver		
Engine Capacity:	1590 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,612.00	4,043.00	1,569.00	27.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,830.00	4,890.00	1,940.00	28.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>12,442.00</b>	<b>8,933.00</b>	<b>3,509.00</b>	<b>28.20</b>
<b>+ GST 7.00/7.00% (S\$)</b>	870.94	625.31	245.63	28.20
<b>Nett Amount (S\$)</b>	<b>13,312.94</b>	<b>9,558.31</b>	<b>3,754.63</b>	<b>28.20</b>

**INSPECTION**

Date of Assignment:	30/11/2022	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (ubi) 330 UBI ROAD 3 Singapore 408650
Date Inspected:	01/12/2022 Inspected At:	
Estimated Period of Repair:	6.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Feb 2023)
<b>Parts:</b>	143	MITSUBISHI LANCER 1.6 EX SPORTS (M) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLP5363T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TYRE YOKOHAMA AE51	Not Necessary	280.00 FS	*- FS
2	1		*FACE ,FR BUMPER	Deformed	739.00 FS	*739.00 FS
3	12		*RIVET ,FR BUMPER	Necessary	48.00 FS	*48.00 FS
4	10		*CLIP,FR BUMPER	Necessary	40.00 FS	*40.00 FS
5	1		*COVER ,HEADLAMP SUPT PANEL	Not Necessary	61.00 FS	*- FS
6	1		*BRACKET ,FR BUMPER SIDE ,LH	Not Necessary	15.00 FS	*- FS
7	1		*BRACKET ,FR BUMPER SIDE ,RH	Deformed	15.00 FS	*15.00 FS
8	1		*GARNISH ,FR BUMPER ,RH	Not Necessary	37.00 FS	*- FS
9	1		*LAMP ASSY ,SIDE MARKET ,RH	Not Necessary	616.00 FS	*- FS
10	1		*LAMP ASSY ,FOG,FR LH	Not Necessary	308.00 FS	*- FS
11	1		*GRILLE ,RADIATOR	Cracked	272.00 FS	*272.00 FS
12	1		*MARK ,THREE-DIA	Not Necessary	39.00 FS	*- FS
13	1		*HEADLAMP ASSY ,RH	Cracked	682.00 FS	*682.00 FS
14	1		*TANK ,WINDSHIELD WASHER	Deformed	91.00 FS	*91.00 FS
15	1		*MOTOR ,WINDSHIELD WASHER	Not Necessary	156.00 FS	*- FS
16	1		*GASKET ,W/SHLD WASHER TANK	Necessary	4.00 FS	*4.00 FS
17	1		*SHIELD ,FR FENDER ,FR RH	Deformed	120.00 FS	*120.00 FS
18	10		*CLIP,SPLASH SHIELD	Necessary	40.00 FS	*40.00 FS
19	1		*FENDER ,FR RH	Bent	528.00 FS	*528.00 FS
20	1		*BRACKET ,FR FENDER ,RH	Bent	14.00 FS	*14.00 FS
21	1		*GARNISH ,FR FENDER RH	Not Necessary	57.00 FS	*- FS
22	1		*WHEEL, DISC	Cut	1,450.00 FS	*1,450.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)** **5,612.00** **4,043.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO APPLY SEALANT KIT ON NEW PANEL	New	160.00	80.00
2	TO APPLY ANTI-CORROSION ON ACCIDENT AFFECTED AREAS	New	200.00	100.00
3	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	180.00	180.00
4	WHEEL BALANCING	New	50.00	50.00
5	TO REPLACE FRT BUMPER ,RHF FENDER ,ETC TO REPAIR RHF SUPPORT PNL ,RHF FENDER APRON ,RHF DOOR PANEL,HOOD STRAIGHTEN ,REFORM ,ALIGN ON RHS ACCIDENT AFFECTED AREAS	New	2,560.00	1,920.00
6	SPRAY PAINTING ON RHS ACCIDENT AFFECTED AREAS	New	3,300.00	2,200.00
7	TO CONDUCT DIAGNOSTIC CHECK ON USING MUT TESTER AND CLEAR TROUBLE COD	New	280.00	280.00
8	CHECK WIRING & ELECTRICAL SYSTEM	New	100.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>6,830.00</b>	<b>4,890.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >