

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFR 6797D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	CUT/TORN	1,083.30	1,083.30
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	452.00	-
1	FRONT BUMPER SIDE RETAINER O/S (CONSISTENT)	CRACKED	48.50	48.50
1	FRONT BUMPER FOG LAMP O/S (CONSISTENT)	NOT NECESSARY	325.00	-
1	FRONT BUMPER FOG LAMP COVER O/S (CONSISTENT)	SCRATCHED	82.00	82.00
1	SET FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	HEADLAMP O/S (CONSISTENT)	CRACKED	1,015.00	1,015.00
1	FRONT FENDER O/S (CONSISTENT)	DENTED	350.60	350.60
1	FRONT FENDER INNER SHIELD FRT O/S (CONSISTENT)	TORN	182.80	182.80
1	SET FRONT FENDER INNER SHIELD CLIPS O/S (CONSISTENT)	NECESSARY	50.00	50.00
1	FRONT SHOCK ABSORBER O/S (CONSISTENT)	BENT	360.80	360.80
1	FRONT KNUCKLE ARM O/S (CONSISTENT)	BENT	402.60	402.60
1	FRONT KNUCKLE ARM BEARING O/S (CONSISTENT)	DAMAGED	225.00	225.00
1	FRONT LOWER ARM O/S (CONSISTENT)	BENT	454.20	454.20
1	WIPER WASHER TANK (CONSISTENT)	DEFORMED	162.80	162.80
1	FRONT DOOR O/S (CONSISTENT)	NOT NECESSARY	925.50	-
1	FRONT SPORT RIM O/S (CONSISTENT)	WARPED	850.00	850.00
	LESS 20% DISCOUNT		-1,404.02	-1,063.52
			5,616.08	4,254.08
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.		60.00	30.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	80.00
	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE.		180.00	120.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.		600.00	380.00
	TO PUTTY & SPRAY PAINTING.		800.00	400.00
			1,810.00	1,030.00
	GRAND TOTAL		7,426.08	5,284.08

Report Ref No. CS/ASM22012004/Unp3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,200.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/ASM22012004/Unp3m4

CHUA KANG SENG
Licensed Appraiser