



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FB7 7041E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SET FORK (CONSISTENT)	BENT	450.00	450.00
1	FORK T-UNDER BRACKET (CONSISTENT)	BENT	220.00	220.00
1	STEERING CONE (CONSISTENT)	NECESSARY	150.00	60.00
1	FRONT SPORT RIM (CONSISTENT)	TO REPAIR SEE LABOUR	250.00	-
1	FRONT DISC BRAKE (CONSISTENT)	NOT NECESSARY	200.00	-
1	FRONT CALIPER (CONSISTENT)	NOT NECESSARY	280.00	-
1	HANDLE BAR (CONSISTENT)	BENT	300.00	168.00
1	HANDLE BRACKET (CONSISTENT)	NOT NECESSARY	250.00	-
1	FRONT FENDER (CONSISTENT)	CUT	180.00	90.00
1	HANDLE GRIP (CONSISTENT)	NOT NECESSARY	80.00	-
1	BRAKE LEVER (CONSISTENT)	CUT	80.00	45.00
1	PHONE HOLDER (CONSISTENT)	NOT NECESSARY	50.00	-
1	HEAD LIGHT (CONSISTENT)	CUT	180.00	180.00
1	HANDLE COVER (CONSISTENT)	CUT	150.00	150.00
1	PANEL COVER (CONSISTENT)	CUT	220.00	220.00
1	SET DAY LIGHT (CONSISTENT)	CRACKED	280.00	145.00
1	BRASKET (CONSISTENT)	CUT	100.00	60.00
1	BRAKE PEDAL (CONSISTENT)	TO REPAIR SEE LABOUR	150.00	-
1	FRONT FOOTREST BAR (CONSISTENT)	BENT	280.00	115.00
1	FRONT FOOTREST RUBBER (CONSISTENT)	TORN	100.00	40.00
1	REAR FOOTREST (CONSISTENT)	SERVICEABLE	150.00	-
1	EXHAUST PIPE (CONSISTENT)	TO REPAIR SEE LABOUR	800.00	-
1	EXHAUST COVER 1 (CONSISTENT)	SCRATCHED	180.00	82.00
1	EXHAUST COVER 2 (CONSISTENT)	TO REPAIR SEE LABOUR	100.00	-
1	REAR BOX (CONSISTENT)	CUT	480.00	250.00
1	REAR FAIRING COVER RIGHT (CONSISTENT)	CUT	200.00	160.00
1	FRONT FAIRING COVER RIGHT (CONSISTENT)	CUT	250.00	180.00
1	REAR SPORT RIM (CONSISTENT)	NOT NECESSARY	280.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TYRES (CONSISTENT) LESS 10% DISCOUNT	NOT NECESSARY	180.00	-
			-657.00	-261.50
			5,913.00	2,353.50
	<b><u>LABOUR</u></b>			
	LABOUR. INCLUSIVE OF THE REPAIR OF FRONT SPORT RIM, BRAKE PEDAL, EXHAUST PIPE & EXHAUST COVER 2.		500.00	300.00
			500.00	300.00
<b>GRAND TOTAL</b>			<b>6,413.00</b>	<b>2,653.50</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,100.00</b>

Report Ref No. CS/ASM22012005/Unp3m4

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.