

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012006/TVP3Q2**Date:** 20/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00098962201		
Claimant Vehicle No :	YQ852Y	Insured Vehicle No :	YQ9000E		
Date of Loss:	30/11/2022	Nature of Claim:	TP	Claim No:	SNM22D208595/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YQ852Y	Engine No:	4P10D65965
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEN (CBU) (M)	Chassis No:	FEB21EA30130
Reg. Date:	24/05/2019 (Man. Year: 2019)	Odometer:	144889 km
Colour:	Green		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195/85 R15 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,635.67	8,591.40	27,044.27	75.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,620.00	2,870.00	5,750.00	66.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,255.67	11,461.40	32,794.27	74.10
Approved Total (Overridden) (S\$)		9,150.00		
(S\$)	44,255.67	9,150.00	35,105.67	79.32
+ GST 8.00/8.00% (S\$)	3,540.45	732.00	2,808.45	79.32
Nett Amount (S\$)	47,796.12	9,882.00	37,914.12	79.32

INSPECTION

Date of Assignment:	06/12/2022	
Date Inspected:	01/12/2022 Inspected At:	Autobacs Car Care (Singapore) Pte Ltd (HQ) 8 Kaki Bukit Ave 4,, #08-45/46 Premier@Kaki Bukit, Singapore 415875
Estimated Period of Repair:	14.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Feb 2023)	
Parts:	N/A	mitsubishi canter 3.0 D FEB21ER4SDEN (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ852Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT CABIN REAR PANEL	Repair	4,870.13 FL	*- FL
2	1		*FRONT CABIN REAR PANEL GLASS RUBBER MOLDING	Not Necessary	307.40 FL	*- FL
3	1		*AIR DUCT	Deformed	465.20 FL	*465.20 FL
4	1		*COOLER HOUSING	Not Necessary	468.60 FL	*- FL
5	1		*EGR PIPE (METAL)	Not Necessary	865.36 FL	*- FL
6	1		*TURBO BOOST CONTROLLER	Not Necessary	824.20 FL	*- FL
7	1		*REAR TAILLAMP RH	Cracked	260.00 FL	*260.00 FL
8	1		*REAR TAILLAMP LH	Not Necessary	260.00 FL	*- FL
9	1		*REAR TAILLAMP BRACKET RH	Bent	120.00 FL	*120.00 FL
10	1		*REAR TAILLAMP BRACKET LH	Not Necessary	120.00 FL	*- FL
11	1		*REAR BOX OPEN DOOR RH	Bent	2,625.00 FS	*1,500.00 FS
12	1		*REAR BOX OPEN DOOR LH	Bent	2,625.00 FS	*1,500.00 FS
13	1		*REAR BOX OPEN DOOR WOODEN (BEHIND) RH	Distorted	650.00 FL	*650.00 FL
14	1		*REAR BOX OPEN DOOR WOODEN (BEHIND) LH	Not Necessary	650.00 FL	*- FL
15	2		*REAR BOX OPEN DOOR LOCK CATCH	Bent	760.00 FL	*560.00 FL
16	2		*REAR BOX OPEN DOOR LOCK ROD	Bent	1,360.00 FL	*960.00 FL
17	1		*REAR BOX COMPANY STICKER	Necessary	1,200.00 FS	*1,000.00 FS
18	1		*REAR STAND PANEL	Bent	1,350.00 FS	*1,200.00 FS
19	3		*REAR CARGO BED CROSSMEMBER	Not Necessary	6,000.00 FL	*- FL
20	1		*REAR CARGO BED END PANEL	Bent	1,800.00 FL	*1,400.00 FL
21	2		*REAR CARGO BED CHASSIS MEMBER	Repair	9,600.00 FL	*- FL
22	8		*UNDER CARRIAGE U BRACKET	Not Necessary	2,000.00 FL	*- FL
23	1		*SLIDING DOOR RH	Repair	3,600.00 FL	*- FL
24	1		*SLIDING DOOR STICKER RH	Not Necessary	2,000.00 FL	*- FL
25	1		*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS
26	1		*REAR BOX DOOR STICKER 60KM/H	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	44,880.89	9,695.20
- List Item Discount on L Items 25.00/25.00% (\$)	9,245.22	1,103.80
Total Parts (\$)	35,635.67	8,591.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	6,000.00	2,200.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	2,000.00	600.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	150.00	30.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	120.00	40.00
5	TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	New	350.00	0.00
Gross Labour Cost (\$\$)			8,620.00	2,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >