

ASS. REC. BY: T. J. M.REF: 05/CT122012006/Tup3.**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8000

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: YQ852YYr Regn: 2019, May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi CanterC.C. 2978Colour: Green

A/C: Insured / Std / NI / NA

Sp. Reading: 144889

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FEB 21 EAS 3130

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6/6 mmL/Bal. 6 mmL/Bal. 6/6 mm

D.O.A. _____

D.O.I. 01/12/22Survey held at Auto basesDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.A. ()

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL



AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@KB Singapore 415875

TEL: 6702 1555

Co. Reg No.: 201500047H GST No.: 201500047H

Email: admin@autobacs.com.sg

TO	: YQ9000E (CHINA TAIPING)	DATE	: 30-11-2022
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: TP CLAIMS
<u>VEHICLE DETAILS</u>		<u>ACCIDENT DETAIL</u>	
VEHICLE NO.	: YQ852Y	DATE	: 30-11-2022
MAKE / MODEL	: MITSUBISHI CANTER	TIME	: 1020HRS

CLAIM DETAIL : PARTS PRICE (\$\$)

S/N	DESCRIPTION	QTY	UNIT LIST	TOTAL LIST
1	FRONT CABIN REAR PANEL	1	\$ 4,870.13	\$ Rx 4,870.13
2	FRONT CABIN REAR PANEL GLASS RUBBER MOLDING	1	\$ 307.40	\$ X 307.40
3	AIR DUCT	1	\$ 465.20	\$? 465.20
4	COOLER HOUSING	1	\$ 468.60	\$? 468.60
5	EGR PIPE (METAL)	1	\$ 865.36	\$? 865.36
6	TURBO BOOST CONTROLLER	1	\$ 824.20	\$? 824.20
7	REAR TAILLAMP RH	1	\$ 260.00	\$ seny 260.00
8	REAR TAILLAMP LH	1	\$ 260.00	\$ x 260.00
9	REAR TAILLAMP BRACKET RH	1	\$ 120.00	\$ bb 120.00
10	REAR TAILLAMP BRACKET LH	1	\$ 120.00	\$ x 120.00
11	REAR BOX OPEN DOOR RH	1	\$ 3,500.00	\$ bt 3,500.00
12	REAR BOX OPEN DOOR LH	1	\$ 3,500.00	\$ bt 3,500.00
13	REAR BOX OPEN DOOR WOODEN (BEHIND) RH	1	\$ 650.00	\$ dis 650.00
14	REAR BOX OPEN DOOR WOODEN (BEHIND) LH	1	\$ 650.00	\$ x 650.00
15	REAR BOX OPEN DOOR LOCK CATCH	2	\$ 380.00	\$ bb 760.00
16	REAR BOX OPEN DOOR LOCK ROD	2	\$ 680.00	\$ bb 1,360.00
17	REAR BOX COMPANY STICKER	1	\$ 1,600.00	\$ seny 1,600.00
18	REAR STAND PANEL	1	\$ 1,800.00	\$? 1,800.00
19	REAR CARGO BED CROSSMEMBER	3	\$ 2,000.00	\$? 6,000.00
20	REAR CARGO BED END PANEL	1	\$ 1,800.00	\$ bt 1,800.00
21	REAR CARGO BED CHASSIS MEMBER	2	\$ 4,800.00	\$ XR 9,600.00
22	UNDER CARRIAGE U BRACKET	8	\$ 250.00	\$? 2,000.00
23	SLIDING DOOR RH	1	\$ 3,600.00	\$? 3,600.00
24	SLIDING DOOR STICKER RH	1	\$ 2,000.00	\$? 2,000.00

TOTAL : \$ 42,203.36
-25% \$ 10,550.84
SUB TOTAL : \$ 31,652.52

1000

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE	1	\$ 50.00	\$ <i>ht</i> ✓ 50.00
2	REAR BOX DOOR STICKER '60KM/H'	1	\$ 50.00	\$ <i>per</i> ✓ 50.00

S/NETT TOTAL : #REF!

CLAIM DETAILS: LABOUR AND SPRAY PAINTING			
TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION		\$ 6,000.00	2000.
TO SPRAY PAINTING ALL THE ACCIDENT PORION & POLISHING AFFECTED AREA		\$ 2,000.00	600
TO APPLY ANTI-RUST & TUFF KOTE		\$ 150.00	30
TO PERFORM LIGHTING & WIRING CHECK		\$ 120.00	40
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD		\$ 350.00	10

LABOUR TOTAL : \$ 8,620.00

TOTAL PARTS :	#REF!
TOTAL LABOUR : \$	8,620.00
TOTAL AMOUNT : #REF!	

Taufik 97495749/62
WP 01/12/22 @ 420pm
taufik @ lkkanto.wn.
1/5 Resuming after repair
12 days

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is **allowed**
- Supplementary form(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: