

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22012007/TNP3Q2**Date:** 05/01/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00151302203

**Claimant Vehicle No :** SBS6172Z **Insured Vehicle No :** SMM1622B

Date of Loss: 27/11/2022 Nature of Claim: TP Claim No: SNM22D208588/C02/TAYHP

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SBS6172Z**

Make & Model: MERCEDES-BENZ CITARO O530, 6.4 D (A) Engine No: 90292609016419

Reg. Date: 27/02/2012 (Man. Year: 2011) Chassis No: WEB62808323123113

Colour: Multi-colour Odometer: 595633 km

Engine Capacity: 6374 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8/8 mm

Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8/8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	33.00	33.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	888.00	888.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>921.00</b>	<b>921.00</b>	<b>0.00</b>	<b>0.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>64.47</b>	<b>64.47</b>	<b>0.00</b>	<b>0.00</b>
<b>Nett Amount (S\$)</b>	<b>985.47</b>	<b>985.47</b>	<b>0.00</b>	<b>0.00</b>

**INSPECTION**

Date of Assignment: 04/01/2023

Date Inspected: 01/12/2022 Inspected At: Sbs Transit Ltd ( Bedok) (HQ)  
1470 BEDOK NORTH AVE 4  
Singapore 489946

Estimated Period of Repair: 2.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Jan 2023)	
Parts:	N/A	MERCEDES-BENZ CITARO O530 6.4 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS6172Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIGNAL LED LIGHT ,AMBER	Cut	31.00 F	*31.00 F
2	2		*TREENAIL	Necessary	2.00 F	*2.00 F
F=Franchise part.						
Total Parts (S\$)					33.00	33.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CONTRACTOR LABOUR COST	New	700.00	700.00
2	WORKSHOP LABOUR COST	New	188.00	188.00
3	ADVERTISEMENT COST (NPA)	New	0.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>888.00</b>	<b>888.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >