

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22012015/AQCE2**Date:** 27/02/2023**REFERENCE**

Insured/Claimant:	Lai Weixiong	Policy No:	1700063086-05	
Date of Loss:	29/11/2022	Nature of Claim:	OD	Claim No: 6823553118SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS8512U		
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Engine No:	CHZ401057
Reg. Date:	09/10/2017 (Man. Year: 2017)	Chassis No:	WAUZZZGAXHA055607
Colour:	Yellow	Odometer:	76131 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$84,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,939.00	3,707.52	3,231.48	46.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,392.00	1,772.00	3,620.00	67.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,331.00	5,479.52	6,851.48	55.56
- Excess (\$\$)	800.00	800.00	0.00	0.00
(\$\$)	11,531.00	4,679.52	6,851.48	59.42
+ GST 8.00/8.00% (\$\$)	922.48	374.36	548.12	59.42
Nett Amount (\$\$)	12,453.48	5,053.88	7,399.60	59.42

INSPECTION

Date of Assignment:	01/12/2022	
Date Inspected:	30/11/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - RH	Dented	2,962.00 FS	*2,369.60 FS
2	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	98.00 FS	*- FS
3	1		*FRONT DOOR CATCH - RH	Not Necessary	134.00 FS	*- FS
4	1		*FRONT DOOR HANDLE - RH	Cut	398.00 FS	*318.00 FS
5	1		*FRONT DOOR HANDLE CAP - RH	Cut	62.00 FS	*48.96 FS
6	1		*FRONT DOOR LOCK CYLINDER WITH HOUSING - RH	Not Necessary	564.00 FS	*- FS
7	1		*FRONT DOOR SLIDE VALVE - RH	Not Necessary	25.00 FS	*- FS
8	1		*FRONT DOOR HANDLE SENSOR - RH	Not Necessary	255.00 FS	*- FS
9	1		*FRONT DOOR UNDERLAY - RH	Not Necessary	6.00 FS	*- FS
10	1		*REAR DOOR UNDERLAY - RH	Not Necessary	7.00 FS	*- FS
11	1		*FRONT DOOR MOUNTING BAR - RH	Not Necessary	178.00 FS	*- FS
12	1		*FRONT DOOR BOWDEN CABLE	Not Necessary	58.00 FS	*- FS
13	1		*FRONT EXTERIOR WING MIRROR MOUNTING - RH	Cut	571.00 FS	*456.80 FS
14	1		*FRONT WING MIRROR CAP - RH	Cut	203.00 FS	*162.40 FS
15	1		*FRONT WING MIRROR GLASS - RH	Not Necessary	325.00 FS	*- FS
16	1		*FRONT DOOR COVER - RH	Cut	270.00 FS	*216.00 FS
17	1		*FRONT TYRE PRESSURE DATA PLATE	Not Necessary	34.00 FS	*- FS
18	1		*REAR DOOR COVER - RH	Not Necessary	238.00 FS	*- FS
19	1		*SUNDRIES	Necessary	400.00 FS	*15.36 FS
20	1		*FRONT WINDOW APERTURE SEAL-RH (Supplementary)	Deformed	151.00 FS	*120.40 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					6,939.00	3,707.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	400.00	280.00
2	TO DISMANTLE AND RENEW RHS FRONT DOOR. TO REPAIR RHS REAR DOOR RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,800.00	500.00
3	TO RESPRAY RHS FRONT DOOR, DOOR HANDLE, RHS DOOR AND RHS WING MIRROR COVER	New	3,000.00	800.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,392.00	1,772.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >