

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI22012016/RQY3Q2**Date:** 27/06/2023**REFERENCE**

Insured/Claimant:	CALL LADE ENTERPRISES PTE LTD	Policy No:	DMCG22009586
Date of Loss:	26/11/2022	Nature of Claim:	OD Claim No: CDMCG22002557

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE6697P		
Make & Model:	SCANIA P410A4X2NZ, 12.7 D (M)	Engine No:	DC13163L017299364
Reg. Date:	30/08/2021 (Man. Year: 2021)	Chassis No:	YS2P4X20005626229
Colour:	Multi-colour	Odometer:	106880 km
Engine Capacity:	12742 cc		
Market Value/New Car Price:	S\$180,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	315/80 R22.5	Rear Tyre Size:	315/80 R22.5 (D)
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8/8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,385.40	19,797.01	4,588.39	18.82
Miscellaneous Items	222.96	222.96	0.00	0.00
Labour	5,810.00	4,040.00	1,770.00	30.46
Paintwork Labour	1,400.00	1,000.00	400.00	28.57
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	31,818.36	25,059.97	6,758.39	21.24
- Excess (\$\$)	0.00	2,500.00	-2,500.00	
(\$\$)	31,818.36	22,559.97	9,258.39	29.10
+ GST 7.00/8.00% (\$\$)	2,227.28	1,804.80	422.48	18.97
Nett Amount (\$\$)	34,045.64	24,364.77	9,680.87	28.43

INSPECTION

Date of Assignment:	01/12/2022 Present Location:	Woon Meng Motor Pte Ltd (Bukit Batok)
Date Inspected:	01/12/2022 Inspected At:	Woon Meng Motor Pte Ltd (Bukit Batok)
Estimated Period of Repair:	10.0 days	50 Bukit Batok Street 23,, #01-06 Midview Building Singapore 659578

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount:\$25,059.96

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Jun 2023)	
Parts:	N/A	SCANIA P410A4X2NZ 12.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE6697P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Cracked	862.84 F	*862.84 F
2	1		*FRONT SUNVISOR TOP	Cracked	224.36 F	*224.36 F
3	1		*FRONT SUNVISOR LOWER	Cracked	266.88 F	*266.88 F
4	1		*FRONT TOP MIRROR	Broken	375.48 F	*375.48 F
5	1		*FRONT WIPER LOWER SIDE GARNISH LH	Missing	87.35 F	*87.35 F
6	1		*FRONT PANEL	Scratched	1,058.93 F	*1,058.93 F
7	1		*SCAN	Necessary	61.24 F	*61.24 F
8	1		*IA	Necessary	51.85 F	*51.85 F
9	1		*FRONT PANEL SIDE GRILLE	Scratched	90.85 F	*90.85 F
10	1		*FRONT LOWER PANEL	Scratched	637.98 F	*637.98 F
11	1		*FRONT INNER PANEL	Not Necessary	2,085.89 F	*- F
12	1		*COVER	Cracked	86.70 F	*86.70 F
13	1		*FRONT PANEL LOCK LH	Not Necessary	39.20 F	*- F
14	1		*FRONT CORNER PANEL LH	Buckled	675.68 F	*675.68 F
15	1		*FRONT HEADLAMP LH	Cracked	1,339.52 F	*1,339.52 F
16	1		*FRONT HEADLAMP GRILLE LH	Bent	128.51 F	*128.51 F
17	1		*FRONT HEADLAMP MEAT LH	Bent	202.66 F	*202.66 F
18	1		*FRONT HEADLAMP GRILLE SIDE COVER LH	Cracked	15.61 F	*15.61 F
19	1		*FRONT BUMPER	Bent	3,247.19 F	*3,247.19 F
20	1		*FRONT BUMPER SIDE COVER LH	Scratched	50.87 F	*50.87 F
21	1		*FRONT FOG LAMP COVER LH	Scratched	28.52 F	*28.52 F
22	1		*FRONT HEADLAMP MEAT HINGE LH	Not Necessary	17.02 F	*- F
23	1		*FRONT CORNER PANEL BRACKET LH	Bent	68.23 F	*68.23 F
24	1		*FRONT CORNER PANEL SEAL LH	Necessary	75.49 F	*75.49 F
25	2		*FRONT CORNER PANEL BRACKET LH	Not Necessary	128.74 F	*- F
26	1		*FRONT DOOR LH	Buckled	3,427.32 F	*3,427.32 F
27	1		*FRONT DOOR SIDE SEAL LH	Necessary	45.12 F	*45.12 F
28	1		*FRONT DOOR LOCK LH	Not Necessary	330.48 F	*- F
29	1		*FRONT DOOR HINGE LH (2 PCS)	Bent	279.58 F	*64.37 F
30	1		*FRONT DOOR INNER TRIM LH	Not Necessary	840.04 F	*- F
31	1		*FRONT DOOR RUBBER LH	Not Necessary	283.05 F	*- F
32	1		*FRONT STEP PANEL LH	Cracked	786.99 F	*786.99 F
33	1		*FRONT HEADLAMP BRACKET LH	Not Necessary	154.02 F	*- F
34	1		*FRONT HEADLAMP SEAL LH	Not Necessary	24.72 F	*- F
35	1		*FRONT TOP MIRROR NOISE ABSORBENT (4 PCS)	Cracked (1 PCS ONLY)	69.56 F	*17.39 F
36	1		*FRONT SUNVIOR SIGNAL LAMP LH	Missing	91.06 F	*91.06 F
37	1		*ROOF TOP PANEL LH	Bent	630.29 F	*630.29 F
Supplementary #1						
38	1		*WIPER TANK	Cracked	197.45 F	*197.45 F
39	1		*FRONT STEP 2ND ALUMINIUM LH	Cut	241.23 F	*241.23 F
40	1		*FRONT WIPER BLADE	Cut	54.62 F	*54.62 F
41	1		*CABLE HARNESS	Cut	109.84 F	*109.84 F
42	1		*FRONT PANEL HANDLE	Cracked	654.78 F	*654.78 F
43	1		*FRONT STEP LOWER GARNISH LH	Cut	140.86 F	*140.86 F
44	1		*FRONT CORNER PANEL INNER BRACKET LH	Bent	77.77 F	*77.77 F

Report was unsubmitted during this print-out.

6/27/23, 2:05 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*FRONT CORNER PANEL HINGE LH	Bent	70.40 F	*70.40 F
46	1		*FRONT HEADLAMP BRACKET LH	Bent	103.29 F	*103.29 F
47	4		*FRONT BUMPER TOP COVER	Necessary	78.56 F	*78.56 F
48	1		*FRONT SUNVIOR TOP BRACKET LH	Missing	20.80 F	*20.08 F
49	1		*FRONT SIDE MIRROR GLASS LH	Cracked	110.00 F	*110.00 F
50	10		*FRONT DOOR WINDOW RIVET	Necessary	15.00 F	*14.90 F
51	1		*FRONT FUEL BOX INNER COVER	Cracked	177.10 F	*177.10 F
52	1		*AIR HOSE HOUSING	Bent	32.34 F	*32.34 F
53	1		*WIRE HOUSING	Bent	159.72 F	*159.72 F
54	1		*FRONT HEADLAMP INNER BRACKET LH	Bent	588.67 F	*588.67 F
55	1		*FRONT ROOF TOP PANEL	Bent	466.30 F	*466.39 F
F=Franchise part.						
Sub Total (\$\$)					22,168.55	17,997.28
+ Margin on L,N Items 10.00/10.00% (\$\$)					2,216.85	1,799.73
Total Parts (\$\$)					24,385.40	19,797.01
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT ERP BRACKET (NECESSARY)	15.00	15.00
2	1	FRONT WINDSCREEN SEALANT (NECESSARY)	207.96	207.96
Sub Total (\$\$)			222.96	222.96

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO PUTTY & SPRAY PAINTING	New	1,400.00	1,000.00
Labour Items				
2	TO REMOVE, REPLACE, REPAIR & REFIX DAMAGED PARTS	New	3,500.00	2,800.00
3	TO R & R ROOF TOP INNER TRIM	New	300.00	200.00
4	TO R & R FRONT DASHBOARD	New	450.00	0.00
5	TO REMOVE & INSTALL DOOR MECHANISM & CHECK FOR FUNCTION	New	250.00	100.00
6	TO R & R FRONT WINDSCREEN GLASS	New	350.00	300.00
7	TO R & R DRIVER SEAT AND PASSENGER SEAT	New	280.00	0.00
8	TO R & R WIRING	New	80.00	40.00
9	TO NUMBERING LOGO	New	600.00	600.00
Gross Labour Cost (\$\$)			7,210.00	5,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >