

Vehicle Damage Assessment Report for [XE6697P]

Estimate Created: 13/06/2023 15:29 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 13/06/2023 16:33 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number	CDMCG22002557
Claim Type	OD		
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number	

Vehicle Information

Brand	Saab	Model	Saab 9-3
Engine Type			
License Plate Number	XE6697P	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- VEHICLE MAKE AND MODEL: SCANIA P410A4X2NZ	Insurlogic 4 (13/06/2023 16:33)
- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK: CONCLUDED THE COST OF REPAIR AT \$25,096.96 WITH 10 WORKING DAYS	Insurlogic 4 (13/06/2023 16:31)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
Front windscreen glass		1	862.84	10.00 %	949.12
Front sunvisor top		1	224.36	10.00 %	246.80
Front sunvisor lower		1	266.88	10.00 %	293.57
Front top mirror		1	375.48	10.00 %	413.03
Front wiper lower side garnish LH		1	87.35	10.00 %	96.09
Front panel		1	1058.93	10.00 %	1,164.82
Scan		1	61.24	10.00 %	67.36
IA		1	51.85	10.00 %	57.04
Front panel side grille		1	90.85	10.00 %	99.94
Front lower panel		1	637.98	10.00 %	701.78
Cover		1	86.70	10.00 %	95.37
LH front corner panel		1	675.68	10.00 %	743.25
LH headlamp		1	1339.52	10.00 %	1,473.47
LH front headlamp grille side cover		1	15.61	10.00 %	17.17
LH front headlamp grille		1	128.51	10.00 %	141.36
LH front headlamp meat		1	202.66	10.00 %	222.93
Front bumper		1	3247.19	10.00 %	3,571.91
Front bumper side cover LH		1	50.87	10.00 %	55.96
LH front bumper fog lamp cover		1	28.52	10.00 %	31.37
LH front corner panel bracket		1	68.23	10.00 %	75.05
LH front corner panel seal		1	75.49	10.00 %	83.04
LH front door side seal		1	45.12	10.00 %	49.63
LH front step panel		1	786.99	10.00 %	865.69
LH front door hinge		1	64.36	10.00 %	70.80
Front sunvisor signal lamp LH		1	91.06	10.00 %	100.17
Roof top panel LH		1	630.29	10.00 %	693.32
Wiper tank		1	197.45	10.00 %	217.20
Front step 2nd aluminium LH		1	241.23	10.00 %	265.35
Front wiper blade		1	54.62	10.00 %	60.08
Cable harness		1	109.84	10.00 %	120.82
Front panel handle		1	654.78	10.00 %	720.26
Front step lower garnish LH		1	140.86	10.00 %	154.95
Front corner panel inner bracket LH		1	77.77	10.00 %	85.55
Front corner panel hinge LH		1	70.40	10.00 %	77.44

Front headlamp bracket LH	1	103.29	10.00 %	113.62
Front bumper top cover	1	78.56	10.00 %	86.42
Front sunvisor top bracket LH	1	20.08	10.00 %	22.09
Front side mirror glass LH	1	110.00	10.00 %	121.00
Front door window rivet	10	1.49	10.00 %	16.39
Front fuel box inner cover	1	177.10	10.00 %	194.81
Air hose housing	1	32.34	10.00 %	35.57
Wire housing	1	159.72	10.00 %	175.69
Front headlamp inner bracket LH	1	588.67	10.00 %	647.54
Front roof top panel	1	466.39	10.00 %	513.03
LH front door	1	3427.32	10.00 %	3,770.05
Adhesive tape	1	17.39	10.00 %	19.13

Parts Subtotal 19,797.03

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Front ERP bracket		1.0	15.00	0.00 %	15.00
Front windscreen sealant		1.0	207.96	0.00 %	207.96

Materials Subtotal 222.96

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
Panel beating	RnR	2800.00	0.00 %	2,800.00
To remove and refit roof top inner trim.	RnR	200.00	0.00 %	200.00
To remove & install door mechanism & check for function.	RnR	100.00	0.00 %	100.00
To remove and refit front windscreen glass.	RnR	300.00	0.00 %	300.00
To remove and refit wiring	RnR	40.00	0.00 %	40.00
To numbering logo	RnR	600.00	0.00 %	600.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	1000.00	0.00 %	1,000.00

Labor Rate

S\$ 50 / Hour

General Labor Subtotal

4,040.00

Paint Labor Subtotal	1,000.00
Labor Subtotal	5,040.00

Summary

Repair Cost	25,059.99
Discount(0 %)	(0.00)
	25,059.99
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	25,059.99