

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22012018/RVY3M4**Date:** 30/12/2022**REFERENCE**

Handling Insurer: ECICS Limited Policy No: MCV22A00007800
Claimant Vehicle No : SMD2989J **Insured Vehicle No :** GBF3123D
 Date of Loss: 18/10/2022 Nature of Claim: TP Claim No: DMCV2200006H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMD2989J**
 Make & Model: MITSUBISHI OUTLANDER, 2.0 CVT (A) Engine No: 4J11YP9397
 Reg. Date: 13/08/2018 (Man. Year: 2018) Chassis No: GF7W0402079
 Colour: Black Odometer: 45822 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,628.40	1,300.50	1,327.90	50.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	830.00	800.00	49.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,258.40	2,130.50	2,127.90	49.97
+ GST 7.00/7.00% (S\$)	298.09	149.14	148.95	49.97
Nett Amount (S\$)	4,556.49	2,279.64	2,276.85	49.97

INSPECTION

Date of Assignment: 30/11/2022
 Date Inspected: 01/12/2022 Inspected At: ETHOZ GROUP LTD
 30 BUKIT BATOK CRESCENT
 SINGAPORE 658075
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2022)
Parts:	M1-SUV	MITSUBISHI OUTLANDER 2.0 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD2989J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	867.00 FN	*867.00 FN
2	1		*REAR BUMPER RETAINER LH	Not Necessary	49.00 FN	*- FN
3	1		*REAR BUMPER BRACKET LH	Not Necessary	92.00 FN	*- FN
4	10		*REAR BUMPER CLIPS	Necessary	50.00 FN	*50.00 FN
5	1		*TAILGATE (NPA)	Repair	0.00 FN	*- FN
6	1		*EMBLEM - OUTLANDER	Necessary	89.00 FN	*89.00 FN
7	1		*TAILGATE LAMP LH	Cracked	439.00 FN	*439.00 FN
8	1		*TAILGATE CHROME GARNISH	Repair	497.00 FN	*- FN
9	1		*TAILLAMP LH	Not Necessary	593.00 FN	*- FN
10	1		*REAR FENDER LH (NPA)	Not Necessary	0.00 FN	*- FN
11	1		*END PANEL (NPA)	Not Necessary	0.00 FN	*- FN
12	1		*REVERSE SENSOR	Not Necessary	220.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	2,896.00	1,445.00
- Nett Item Discount on N Items 10.00/10.00% (\$)	267.60	144.50
Total Parts (\$)	2,628.40	1,300.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	800.00	400.00
2	TO RESPRAY AFFECTED AREAS	New	800.00	400.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	30.00
Gross Labour Cost (S\$)			1,630.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >