



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGD 8448K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	545.90	545.90
1	REAR BUMPER SIDE HOLDER LH	NOT NECESSARY	54.50	-
1	REAR BUMPER REFLECTOR LH	CUT	74.80	74.80
1	REAR BUMPER REINFORCEMENT	DENTED	395.10	395.10
1	REAR END PANEL	TO REPAIR SEE LABOUR	695.30	-
	LESS 25% DISCOUNT		-441.40	-253.95
			1,324.20	761.85
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
1	SET REAR END PANEL SEALANT (SN)	NOT NECESSARY	60.00	-
			370.00	30.00
	<u>LABOUR</u>			
	PANEL BEATING, REMOVE AND REFIT PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		600.00	250.00
	SPRAY PAINTING TO AFFECTED AREA.		600.00	250.00
	WIRING CHECK.		50.00	30.00
	TO APPLY TUFF COAT.	NOT NECESSARY	150.00	-
	TO REMOVE REVERSE SENSOR.		100.00	50.00
	TO REMOVE UPHOLSTERY.	NOT NECESSARY	150.00	-
			1,650.00	580.00
GRAND TOTAL			3,344.20	1,371.85
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,100.00

Report Ref No. CS/SPF22012028/Avy3m4

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,100-\$1,500

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.