



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 5353C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER (WCP)	DENTED	950.00	950.00
10	FRT BUMPER CLIP (WCP)	NECESSARY	30.00	30.00
1	FRT BUMPER REINFORCEMENT (INDENT) (WCP)	BENT	480.00	480.00
1	FRT BUMPER CTR GRILLE (BIG) (WCP)	TORN	750.00	750.00
1	FRT BUMPER LWR GRILLE (WITH TOW COVER) (WCP)	TORN	580.00	580.00
1	FRT BUMPER SIDE COVER RH (INDENT) (WCP)	TORN	185.00	185.00
1	FRT FENDER RH -PLASTIC (INDENT) (WCP)	TO REPAIR SEE LABOUR	760.00	-
1	HEADLAMP RH (INDENT) (WCP)	NOT NECESSARY	4,200.00	-
1	FRT GRILLE (WCP)	NOT NECESSARY	580.00	-
1	FRT RH FENDER INNER COWLING (WCP) (ADDITIONAL)	TORN	185.00	185.00
10	INNER COWLING CLIPS (WCP) (ADDITIONAL)	NECESSARY	20.00	20.00
	COST PLUS 10%		872.00	318.00
			9,592.00	3,498.00
	<u>LABOUR</u>			
	WIRE CHECKING.		30.00	20.00
	LABOUR CHARGE. INCLUSIVE OF THE REPAIR OF FRT FENDER RH -PLASTIC (INDENT).		600.00	400.00
	SPRAY PAINTING.		650.00	480.00
			1,280.00	900.00
	GRAND TOTAL		10,872.00	4,398.00

RECOMMENDED COST OF REPAIRS			4,398.00
LESS EXCESS			-750.00
NETT LIABILITY			3,648.00

Report Ref No. CS/UOI22012029/Uwy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.