

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## TAX INVOICE

LONPAC INSURANCE BHD INV No. AC2304385

300 BEACH ROAD INV Date 11/07/2023

#17-04/07 THE CONCOURSE Reference CC4/LPC22012036/Kpa3q2

SINGAPORE 199555 Code LPC2

#### PROFESSIONAL SERVICE FEE

Vehicle No. SLE 3561J

Insured Veh. XD 5135G

Claim No. 22/22/VC05/026647

Policy No. Z22VC05014861

Accident Date 30/11/2022

Inspection Date 12/12/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

**LKM** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LONPAC INSURANCE BHD		Ref:	CC4/LPC22012036/Kpa3q2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date:	11/07/2023	
			Code:	LPC2	
1.		Policy Particulars :	- THIRD PARTY CLAIN	Л	
	Insured Veh.	XD 5135G	Veh. Inspected	SLE 3561J	
	Policy No.	Z22VC05014861	Coverage (\$)	0.00	
	Claim No.	22/22/22/VC05/026647	Excess (\$)	0.00	
	Assign From	GERALD	Assign Date	01/12/2022	
2.		Vehicle Partic	ulars & Condition		
	Make & Model	MERCEDES BENZ GLC250 (A)	c.c	1991	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	WDC2539462F084676	Colour	METALLIC GREY	
	Odometer	68161 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.		Condition	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	235/55 R19	PIRELLI	6 mm	
	L/H Front Tyre	235/55 R19	PIRELLI	6 mm	
	R/H Rear Tyre	235/55 R19	PIRELLI	6 mm	
	L/H Rear Tyre	235/55 R19	PIRELLI	6 mm	
4.		Description	on of Damages		
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.		General	Information		
	Accident Date	30/11/2022	Inspection Date	12/12/2022	
	Survey held at	MBM WHEELPOWER PTE LTD			
		160 SIN MING DRIVE #06-02 SIN MING AUTOCITY SINGAPORE 575722			
5a.		Re	emarks		
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	5 Work	ing Days	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 3561J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	BENT	3,050.00	2,525.00
1	TAILGATE WEATHERSTRIP	SERVICEABLE	480.00	-
1	TAILGATE HINGE LH	TO REPAIR SEE LABOUR	240.00	-
1	TAILGATE HINGE RH	TO REPAIR SEE LABOUR	240.00	-
1	TAILGATE LOCK	TO REPAIR SEE LABOUR	300.00	-
1	TAILGATE MERCEDES LOGO	NECESSARY	60.00	60.00
1	TAILGATE "GLC 250" EMBLEM	NECESSARY	100.00	100.00
1	TAILGATE "4 MATIC" EMBLEM	NECESSARY	140.00	110.00
1	TAILGATE LAMP LH	SERVICEABLE	550.00	-
1	TAILGATE LAMP RH	SERVICEABLE	550.00	-
1	TAIL LAMP LH	SERVICEABLE	580.00	-
1	TAIL LAMP RH	SERVICEABLE	580.00	-
1	REAR BUMPER	BENT	950.00	950.00
1	REAR BUMPER TOWING COVER	SERVICEABLE	75.00	-
1	REAR BUMPER RETAINER LH	SERVICEABLE	100.00	-
1	REAR BUMPER RETAINER LH	SERVICEABLE	100.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	840.00	-
1	REAR BUMPER SENSOR	SERVICEABLE	1,000.00	-
1	REAR BUMPER CLIP	NECESSARY	80.00	80.00
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	50.00	-
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	50.00	-
1	REAR BUMPER LOWER DIFFUSER	DENTED	750.00	650.00
1	REAR BUMPER LOWER DIFFUSER TRIM	DENTED	450.00	450.00
1	END PANEL	TO REPAIR SEE LABOUR	1,700.00	-
1	END PANEL TOP GARNISH	SERVICEABLE	390.00	-
1	REAR BUMPER REINFORCEMENT	BUCKLED	446.00	250.00
	LESS 10% DISCOUNT		-1,385.10	-517.50
			12,465.90	4,657.50

Report Ref No. CC4/LPC22012036/Kpa3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	NUMBER PLATE & HOLDER (SN)	SERVICEABLE	50.00	-
1	BODY SEALANT (SN)	NOT NECESSARY	50.00	-
			100.00	-
	<u>LABOUR</u>			
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF TAILGATE HINGE LH, TAILGATE HINGE RH, TAILGATE LOCK AND END PANEL.		1,600.00	400.00
	TO CHECK & RECONNECT ALL NECESSARY WIRING.		80.00	20.00
	TO REMOVE & REFIT ALL SENSOR.		150.00	60.00
	TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)	NOT NECESSARY	250.00	-
	TO APPLY ANTI-RUST.		80.00	30.00
	TO SPRAY PAINT ON THE AFFECTED AREAS.		1,600.00	660.00
			3,760.00	1,170.00
	GRAND TOTAL		16,325.90	5,827.50

RECOMMENDED COST OF REPAIRS 5,827.50

Report Ref No. CC4/LPC22012036/Kpa3q2

KONG SENG CHEONG

**Licensed Appraiser** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SLE 3561J

### **INSPECTION**















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SLE 3561J

### **RE-INSPECTION**











