

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22012038/UYA3Q2**Date:** 18/02/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210009162
Claimant Vehicle No :	SLW1718T	Insured Vehicle No :	SKB37D
Date of Loss:	30/11/2022	Nature of Claim:	TP
		Claim No:	6282106994SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW1718T		
Make & Model:	TOYOTA HARRIER, 2.0 G GRADE (A)	Engine No:	8ARZ107038
Reg. Date:	31/01/2018 (Man. Year: 2017)	Chassis No:	JTEKB3GH90J001220
Colour:	Silver	Odometer:	99967 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,474.77	8,689.07	5,785.70	39.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,730.00	2,960.00	1,770.00	37.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,204.77	11,649.07	7,555.70	39.34
Approved Total (Overridden) (S\$)		9,300.00		
(S\$)	19,204.77	9,300.00	9,904.77	51.57
+ GST 7.00/7.00% (S\$)	1,344.33	651.00	693.33	51.57
Nett Amount (S\$)	20,549.10	9,951.00	10,598.10	51.57
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,753.00		

INSPECTION

Date of Assignment:	01/12/2022		
Date Inspected:	01/12/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	7.0 days		

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LID	Dented / Warped	2,580.00 FL	*1,816.10 FL
2	1		*TAILGATE LID HARRIER BADGE	Necessary	110.00 FL	*62.20 FL
3	1		*TAILGATE LID LOCK	Not Necessary	974.00 FL	*- FL
4	1		*TAILGATE LID WEATHERSTRIP	Not Necessary	442.00 FL	*- FL
5	1		*N/S TAILGATE LID REFLECTOR	Cracked	498.00 FL	*498.00 FL
6	1		*TAILGATE LID INNER TRIMBOARD	Not Necessary	578.00 FL	*- FL
7	1		*TAILGATE LID KEYLESS SENSOR	Not Necessary	100.00 FL	*- FL
8	1		*REAR WINDSCREEN MOULDING	Necessary	180.60 FL	*166.60 FL
9	1		*REAR BUMPER	Distorted	1,415.00 FL	*931.00 FL
10	1		*REAR BUMPER SIDE RETAINER	N/S Bent	170.00 FL	*85.00 FL
11	1		*REAR BUMPER SIDE HOLDER	N/S Cracked	50.00 FL	*25.00 FL
12	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
13	1		*REAR BUMPER LOWER	Distorted	455.00 FL	*455.00 FL
14	1		*REAR BUMPER LOWER REFLECTOR N/S	Not Necessary	57.60 FL	*- FL
15	1		*REAR BUMPER SPONGE	Torn	125.00 FL	*125.00 FL
16	1		*REAR BUMPER END SPLASHELD COVER (N/S)	Torn	75.00 FL	*75.00 FL
17	1		*N/S REAR LAMP	Broken	765.00 FL	*765.00 FL
18	2		*N/S REAR LAMP CLIP HOLDER	Not Necessary	9.00 FL	*- FL
19	1		*REAR END PANEL	Badly Dented	625.00 FL	*625.00 FL
20	1		*REAR END PANEL INNER TRIM	Not Necessary	445.00 FL	*- FL
21	4		*REAR END PANEL INNER TRIM CLIPS	Not Necessary	18.00 FL	*- FL
22	1		*N/S ROCKER PANEL GARNISH	Grazed	550.00 FL	*550.00 FL
23	1		*N/S REAR FENDER	Badly Dented	1,446.30 FL	*1,446.30 FL
24	1		*N/S REAR FENDER INNER COWLING	Not Necessary	522.50 FL	*- FL
25	10		*N/S REAR FENDER INNER COWLING CLIPS	Not Necessary	50.00 FL	*- FL
26	1		*N/S REAR FENDER WIND DEFLECTOR	No such part	89.80 FL	*- FL
27	1		*N/S FRONT DOOR	Badly Dented	1,489.00 FL	*1,489.00 FL
28	1		*N/S FRONT DOOR HINGE -TOP	Not Necessary	88.00 FL	*- FL
29	1		*N/S FRONT DOOR HINGE -BOTTOM	Not Necessary	88.00 FL	*- FL
30	1		*N/S FRONT DOOR CHROME MOULDING	Lower Cracked	120.00 FL	*120.00 FL
31	1		*N/S FRONT DOOR OUTER MOULDING	Not Necessary	210.00 FL	*- FL
32	1		*N/S REAR DOOR	Repair	1,396.00 FL	*- FL
33	1		*N/S REAR DOOR CHROME MOULDING	Lower Scratched	120.00 FL	*120.00 FL
34	1		*AIR VENT N/S	Distorted	121.00 FL	*121.00 FL
35	1		*N/S REAR FENDER QUARTER GLASS SEALANT	Necessary	50.00 FS	*30.00 FS
36	1		*TUBE REAR WINDSCREEN GLASS SEALANT	Necessary	180.00 FS	*40.00 FS
37	1		*REAR WINDSCREEN GLASS INNER SPONGE SEAL	Necessary	100.00 FS	*40.00 FS
38	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS
39	1		*BACKOFF CAMERA LEN	Not Necessary	400.00 FS	*- FS
40	1		*SET REAR BUMPER PARKING SENSOR	Shorted	450.00 FS	*200.00 FS
41	1		*REAR AIR VENT INNER GARNISH N/S	Twisted	108.50 FL	*108.50 FL
42	1		*REAR TOOLS TRAY N/S	Cracked	345.20 FL	*345.20 FL
43	1		*TAILLAMP HOUSING PANEL N/S	Dented	408.10 FL	*408.10 FL
44	1		*REAR DAMPER SUSP TOWER	Bent / Twisted	785.10 FL	*785.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,889.70	11,482.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,414.93	2,793.03
Total Parts (\$\$)	14,474.77	8,689.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	140.00	120.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	500.00	100.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	120.00	30.00
4	TO TRANSFER OF N/S BOTH DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST	New	200.00	60.00
5	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	150.00	50.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	150.00	80.00
7	TO TRANSFER OF TAILGATE FITTINGS ,FIXTURE AND PERFORM WATERSEEPAGE TEST	New	120.00	60.00
8	TO REMOVE AND REFIT N/S REAR FENDER QUARTER GLASS	New	150.00	60.00
9	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,600.00	1,200.00
10	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	1,200.00
Gross Labour Cost (S\$)			4,730.00	2,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >