

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22012039/KYA3Q2**Date:** 07/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220082481
Claimant Vehicle No :	SMX2453H	Insured Vehicle No :	SKP61J
Date of Loss:	29/11/2022	Nature of Claim:	TP
		Claim No:	9541821473SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX2453H	Engine No:	2ZR2G13838
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Chassis No:	JTDZS3EU10J054125
Reg. Date:	31/12/2020 (Man. Year: 2019)	Odometer:	110744 km
Colour:	Metallic Brown		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Firenza 9 mm	Rear Left Side:	Firenza 9 mm
Front Right Side:	Firenza 9 mm	Rear Right Side:	Firenza 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,003.92	41.92	962.00	95.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	550.00	650.00	54.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	2,203.92	591.92	1,612.00	73.14
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	01/12/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	01/12/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint
Estimated Period of Repair:	2.0 days	Singapore 568047

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Repair	921.50 FL	*- FL
2	1		*FRONT FENDER HYBRID EMBLEM LH	Necessary	55.90 FL	*55.90 FL
3	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	79.20 FL	*- FL
4	1		*FRONT BUMPER INNER SHIELD LH	Serviceable	175.30 FL	*- FL
5	1		*FRONT BUMPER (NPA)	Repair	0.00 FL	*- FL
6	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
7	1		*FRONT FENDER INNER SHIELD CLIPS LH	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,311.90	55.90
- List Item Discount on L Items 25.00/25.00% (S\$)	307.98	13.98
Total Parts (S\$)	1,003.92	41.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, REPLACE ,REFIX ,REPAIR & READJUST ACCIDENT AREAS	New	500.00	150.00
2	LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS	New	600.00	400.00
3	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	100.00	0.00
Gross Labour Cost (S\$)			1,200.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >