



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 3033X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR WINDSCREEN GLASS	BROKEN	960.00	960.00
1	INSCRIPTION LOGO (MAN REAR WORDS)	NECESSARY	89.18	89.18
1	GIVE WAY STICKER	NECESSARY	40.00	40.00
1	"SG BUS" STICKER (S)	NECESSARY	100.00	100.00
1	"TOWER TRANSIT" STICKER (S)	NECESSARY	40.00	40.00
4	SIKAFLEX BLACK (SEALANT)	NECESSARY	128.00	128.00
1	60KM/HR STICKER	NECESSARY	6.00	6.00
			1,363.18	1,363.18
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACE: -ITEM NOS.1-7. }		1,950.00	1,300.00
	TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS: -REAR ENGINE DOOR -REAR BUMPER. }		1,300.00	-
	SPRAY PAINTING: -REAR ENGINE DOOR -REAR BUMPER.		1,280.00	1,280.00
			4,530.00	2,580.00
	GRAND TOTAL		5,893.18	3,943.18
RECOMMENDED COST OF REPAIRS				3,943.18

Report Ref No. CS/LIP22012043/Rwy3e2

MARKET VALUE: NA (EST)-LTA REIMBURSEMENT VALUE: \$0.00=NETT VALUE: NA (BUS TOWER TRANSIT)

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.