



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI22012044/Tvy3e2 Date: 11/04/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBF 42Z	Veh. Inspected	GBE 1770D
Policy No.	D22099240	Coverage (\$)	0.00
Claim No.	D22003800MFCV	Excess (\$)	0.00
Assign From	HARMINDER KAUR	Assign Date	01/12/2022
2. Vehicle Particulars & Condition			
Make & Model	SSANGYONG ACTYON D/CAB	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KPADA1ETSFP238977	Colour	GREY
Odometer	236608 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/75 R16	YOKOHAMA	6 mm
L/H Front Tyre	225/75 R16	YOKOHAMA	6 mm
R/H Rear Tyre	225/75 R16	YOKOHAMA	6 mm
L/H Rear Tyre	225/75 R16	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/11/2022	Inspection Date	05/12/2022
Survey held at	38 Woodlands Road #03-14, Woodlands Ind Park E1		
Repairer	TWIN WHEELS AUTO TRADING ENTERPRISE		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	