

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear bumper <i>de ✓</i>	-10%	1678.00	1560
2	Rear bumper side retainer LH/RH@2*\$168 <i>Xm</i>		336.00	
1	Rear reinforcement <i>? Xm</i>		701.00	
2	Rear reverse sensor LH/RH@2*\$245 <i>Xm</i>		490.00	
			3205.00	
			-320.50	
			2884.50	
SPECIAL NETT ITEMS				
1	Rear bumper clips <i>re ✓</i>		35.00	
Total Parts			2919.50	



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Vehicle No. SLE1905P VOLKSWAGEN JETTA 1.4

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	400.00	200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	400.00	200
3	To remove and replace rear reverse sensor	100.00	40
4	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00	XRM 440
Labour Total :		960.00	
TOTAL (PARTS & LABOUR):		3879.50	

1404
35.00
440.00
1879.00
200
1503.20
4/5 - 1,500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
4p 900/10068
2 days
4/5
12/12/22 @ 1430
Resurvey after repair